

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009604/KVY3Q2  
**Date:** 02/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00034822201
<b>Claimant Vehicle No :</b>	SME2438C	<b>Insured Vehicle No :</b>	GBF8545L
Date of Loss:	14/09/2022	Nature of Claim: TP	Claim No: SNM22D206933/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SME2438C</b>	Engine No:	LEB5600959
Make & Model:	HONDA FREED, 1.5 G (A)	Chassis No:	GB71067649
Reg. Date:	24/09/2018 (Man. Year: 2018)	Odometer:	55758 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	570.00	550.00	20.00	3.51
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	243.60	197.40	46.20	18.97
Paintwork Labour	299.31	299.31	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,212.91</b>	<b>1,146.71</b>	<b>66.20</b>	<b>5.46</b>
<b>+ GST 7.00/7.00% (S\$)</b>	84.90	80.27	4.63	5.45
<b>Nett Amount (S\$)</b>	<b>1,297.81</b>	<b>1,226.98</b>	<b>70.83</b>	<b>5.46</b>

**INSPECTION**

Date of Assignment:	29/09/2022	Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	19/10/2022	Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	3.0 days		

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2022)
<b>Parts:</b> M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SME2438C)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		570.00 F	*550.00 F
					<b>Total Parts (\$\$)</b>	<b>570.00</b>
						<b>550.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	Miscellaneous	100.00	100.00
			<b>Sub Total (\$\$)</b>	<b>100.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	Total Paint Including Material	New	299.31	299.31
<b>Labour Items</b>				
2	Total of Labour	New	243.60	197.40
			<b>Gross Labour Cost (\$\$)</b>	<b>542.91</b>
				<b>496.71</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >