



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2301934
3 ANSON ROAD #16-00	INV Date	28/03/2023
SPRINGLEAF TOWER	Reference	CC3/CTI22009609/Kya3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SHB 1161G
Insured Veh.	SKC 7332A
Claim No.	SNM22D206931/C02
Policy No.	DMPCSNW00199332101
Accident Date	28/09/2022
Inspection Date	29/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC3/CTI22009609/Kya3q2 Date: 28/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKC 7332A	Veh. Inspected	SHB 1161G
Policy No.	DMPCSNW00199332101	Coverage (\$)	0.00
Claim No.	SNM22D206931/C02	Excess (\$)	0.00
Assign From		Assign Date	29/09/2022
2. Vehicle Particulars & Condition			
Make & Model	M.G. MG5 (A)	c.c	0
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	LSJE24031MG051357	Colour	GREEN
Odometer	98228 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	8 mm
L/H Front Tyre	205/60 R16	WEST LAKE	8 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	8 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	8 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	28/09/2022	Inspection Date	29/09/2022
Survey held at	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1161G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LINER ASM-RR W/H PNL - LH (DISC 10%)	DISTORTED	83.72	75.35
1	FASCIA-RR BPR (DISC 10%)	BENT	758.48	682.63
1	FASCIA-RR BPR LWR (DISC 10%)	DENTED	230.68	207.61
1	FINISHER-RR BPR - LH (DISC 10%)	DENTED	47.42	42.68
1	BRACKET ASM-RR BPR FASCIA SI-L (DISC 10%)	DISTORTED	29.85	26.87
1	LAMP ASM-RR FOG - LH (DISC 10%)	CRACKED	36.30	32.67
1	BAR ASM-RR BPR IMP (DISC 10%)	BENT	339.76	305.78
1	DOOR ASM-RR SI -L	NOT NECESSARY	2,185.04	-
1	PANEL-BODY SI OTR-L	NOT NECESSARY	1,747.82	-
1	STICKER ELECTRIC (LOGO	NOT NECESSARY	21.60	-
1	BRACKET-RR BPR FASCIA SI MTG - LH	NOT NECESSARY	46.08	-
1	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	NOT NECESSARY	13.20	-
1	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	NOT NECESSARY	12.90	-
1	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	NOT NECESSARY	12.90	-
1	BRACKET-RR BPR FASCIA LWR MTG - LH	NOT NECESSARY	12.80	-
1	BOLT/SCREW-FRT W/H LNR RET	NOT NECESSARY	0.52	-
1	BAR ASM-RR BPR IMP	NOT NECESSARY	339.76	-
1	LAMP ASM-TAIL(BODY SI) - LH	NOT NECESSARY	764.08	-
1	LAMP ASM-TAIL(LID SI) - LH	NOT NECESSARY	407.68	-
			7,090.59	1,373.59
LABOUR				
PANEL BEATING AND BODY WORK.			2,400.00	450.00
SPRAY PAINT.			1,514.00	590.00
TO WASH AND VACUUM.			60.00	-
TO CHECK WIRING AND SYSTEM FUNCTION.			120.00	20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			100.00	-
TO TEST AND REFIX REVERSE SENSOR SYSTEM.			120.00	50.00
TO REPLACE SUNDRY PARTS.			100.00	-

Report Ref No. CC3/CTI22009609/Kya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK & RESET SYSTEM FUNCTION. ISOLATED OF (EV) (NET).		350.00	150.00
			150.00	150.00
			4,914.00	1,410.00
GRAND TOTAL			12,004.59	2,783.59
RECOMMENDED COST OF REPAIRS				2,783.59

Report Ref No. CC3/CTI22009609/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1161G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



SAIC MOTOR CO.,LTD.		
LSJE24031MG051357		
	2016	kg
	N/A	kg
1-	1100	kg
2-	1050	kg
PAINT 5WSD		TRIM 6ASH

MG	
Tyre Pressure:	
205/60 R16 92	
205/60 R16 96	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1161G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1161G

RE-INSPECTION

