





## Case Details

**Case Reference Number :**  
TAX/09/22/2073

**Type of Repair :** Accident Repair

**Vehicle Registration Number :**  
SHB1161G

**Company Type :** Strides Taxi Pte Ltd

**Estimation ID :** EST-19449-ID

**Assigned By :** Taxi Claims Manager  
Team

**Insurance Company Name :** China Taiping Insurance (Singapore)  
Pte Ltd

**Accident Date and Time :** 28/09/2022 01:49 AM

**Vehicle Age(In Months) :** -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks	
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
Standard	Main			DOOR ASM-RR SI -L	1	2,185.04	2,185.04	10.00	1,966.54	Replace	0	0	Not Give	▼	
Standard	Main			PANEL-BODY SI OTR-L	1	1,747.82	1,747.82	10.00	1,573.04	Replace	0	0	Not Give	▼	
Standard	Main			STICKER ELECTRIC ( LOGO	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	▼	
Standard	Main			LINER ASM-RR W/H PNL - LH	1	83.72	83.72	10.00	75.35	Replace	1	75.35	Replace	▼	<i>Di ✓</i>
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	10.00	682.63	Replace	1	682.6	Replace	▼	<i>Bj ✓</i>
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	10.00	207.61	Replace	1	207.6	Replace	▼	<i>Red ✓</i>
Standard	Main			FINISHER-RR BPR - LH	1	47.42	47.42	10.00	42.68	Replace	1	42.68	Replace	▼	<i>Red ✓</i>
Standard	Main			BRACKET ASM-RR BPR FASCIA SI-L	1	29.85	29.85	10.00	26.87	Replace	1	26.87	Replace	▼	<i>Di ✓</i>
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - LH	1	46.08	46.08	10.00	41.47	Replace	0	0	Check	▼	
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) -	1	13.20	13.20	10.00	11.88	Replace	0	0	Check	▼	
							<b>Total Spare Part Cost</b>	<b>10.00</b>	<b>6,082.12</b>			<b>Surveyor Total</b>	<b>1,067.81</b>		
							<b>Lump Sum Discount (%)</b>		<b>0.00</b>			<b>Lump Sum Dis (%)</b>	<b>0</b>		
							<b>Final Spare Part Cost</b>		<b>6,082.12</b>			<b>Final Sur Total</b>	<b>1,067.81</b>		

Standard BOM Type	Main Costing Type	Portion	Material Number	LH SMRT Recommendation BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - CTE	1 Qty	12.90 List Price Per Unit(\$)	12.90 List Price(\$)	10.00 Dis(%)	11.61 Final Price(\$)	Replace Repair/ Replace	0 Surveyor Quantity	Surveyor Approval		Remarks
												0 Surveyor Final Price(\$)	Check Repair/Replace	
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - RH	1	12.90	12.90	10.00	11.61	Replace	0	0	Not Give	▼
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - LH	1	12.80	12.80	10.00	11.52	Replace	0	0	Check	▼
Standard	Main			BOLT/SCREW-FRT W/H LNR RET	10	0.52	5.20	10.00	4.68	Replace	0	0	Check	▼
Standard	Main			BAR ASM-RR BPR IMP	1	339.76	339.76	10.00	305.78	Replace	0	0	Check	▼
Standard	Main			LAMP ASM-TAIL(BODY SI) - LH	1	764.08	764.08	10.00	687.67	Replace	0	0	Not Give	▼
Standard	Main			LAMP ASM-TAIL(LID SI) - LH	1	407.68	407.68	10.00	366.91	Replace	0	0	Not Give	▼
Standard	Main			LAMP ASM-RR FOG - LH	1	36.30	36.30	10.00	32.67	Replace	1	32.67	Replace	▼ <i>CAI ✓</i>
<b>Total Spare Part Cost</b>									6,082.12	<b>Surveyor Total</b>		1,067.81		
<b>Lump Sum Discount (%)</b>									0.00	<b>Lump Sum Dis (%)</b>		0		
<b>Final Spare Part Cost</b>									6,082.12	<b>Final Sur Total</b>		1,067.81		

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	1,800.00	250.00	
<b>Total:</b>			1,800.00	250.00	

**Spray Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	428.00	220	
2	Main	TO RESPRAY REAR FENDER LH	428.00	0	
3	Main	TO RESRAY REAR DOOR LH	428.00	0	
<b>Total:</b>			1,284.00	220.00	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	50	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
6	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
7	Main	ISOLATED OF (EV) (NET)	150.00	150	
<b>Total:</b>			<b>1,000.00</b>	<b>370.00</b>	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,082.12	1,067.81
Total Labour Cost	1,800.00	250.00
Total Spray Painting	1,284.00	220.00
Other	1,000.00	370.00
Overall Total	10,166.12	1,907.81
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	1,907.81
Surveyor Approved Amount		1,907.81
No of Repair Days*	6	2
Remarks	<p><b>LKK Auto Consultants hence notify the Repairer of the following:</b></p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>PART BY PART / Before paint photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email :</p> <p>Acknowledged by Repairer Signature: _____ Date: _____</p>	
Surveyor Name		Kenneth Kong (LKK)
Signature		

Save Clear

Survey Date 29/09/2022