

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009615/KNY3Q2**Date:** 31/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00006562200

**Claimant Vehicle No :** SFP2281L**Insured Vehicle No :** PC3918C

Date of Loss: 23/09/2022

Nature of Claim: TP

Claim No: SNM22D206892/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SFP2281L**

Make &amp; Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FMMU048865

Reg. Date: 28/07/2021 (Man. Year: 2021)

Chassis No: KMHLN41ETNU213801

Colour: Metallic Blue

Odometer: 17613 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Hankook 8 mm

Rear Left Side: Hankook 8 mm

Front Right Side: Hankook 8 mm

Rear Right Side: Hankook 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,609.76	1,083.04	526.72	32.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,130.00	900.00	44.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,639.76</b>	<b>2,213.04</b>	<b>1,426.72</b>	<b>39.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,639.76</b>	<b>1,700.00</b>	<b>1,939.76</b>	<b>53.29</b>

**INSPECTION**

Date of Assignment: 29/09/2022

Date Inspected: 05/10/2022 Inspected At:

Lim Yew Boo Spray Paint Co (HQ)  
Blk 10 Sin Ming Industrial Estate, #01-10  
Singapore 575645

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 Oct 2022)
<b>Parts:</b>	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFP2281L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	470.80 FL	*- FL
2	1		*REAR BUMPER RETAINER /RH	Serviceable	28.00 FL	*- FL
3	3		*REAR BUMPER FASTENER	Serviceable	15.00 FL	*- FL
4	3		*REAR BUMPER EXTENSION FASTENER	Serviceable	15.00 FL	*- FL
5	3		*REAR BUMPER EXTENSION GROMMET SCREW	Not Necessary	15.00 FL	*- FL
6	1		*REAR RIM /RH	Dented	843.40 FL	*728.80 FL
7	1		*REAR ABSORBER /RH	Bent	230.50 FL	*230.50 FL
8	1		*REAR BEARING C/W HUP	Bent / Necessary	394.50 FL	*394.50 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,012.20</b>	<b>1,353.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	402.44	270.76
<b>Total Parts (\$\$)</b>	<b>1,609.76</b>	<b>1,083.04</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	New	120.00	0.00
2	TO CHECK COMPUTERISED WHEEL ALIGNMENT	New	120.00	60.00
3	TO CHECK WATER SEEPAGE	New	60.00	0.00
4	LABOUR TO REMOVE & RE-ASSEMBLE UNDERCARRIAGE PARTS	New	280.00	160.00
5	TO REMOVE ,CHECK,REPAIR & REPLACE RIM	New	150.00	20.00
6	TO REPAIR ,PANEL BEAT ON RIGHT REAR FENDER & LABOUR TO REPLACE THE ABOVE PARTS	New	600.00	450.00
7	TO PUTTY ,PRIMER & SPRAY PAINT ON REAR BUMPER ,RIGHT REAR FENDER & AFFECTED REAR DOOR USING 2K PAINT	New	700.00	440.00
Gross Labour Cost (S\$)			2,030.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >