



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JRD 8440

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET FORK	BENT / TWISTED	450.00	450.00
1	FORK T-UNDER BRACKET	BENT / TWISTED	300.00	180.00
1	FRONT SPORT RIM	WARPED	350.00	300.00
1	FRONT FENDER	CRACKED	180.00	80.00
1	FRONT TYRES SHAFT	NOT NECESSARY	150.00	-
1	FRONT DISC BRAKE	NOT NECESSARY	150.00	-
1	CHASIS ALIGNMENT	NOT NECESSARY	500.00	-
1	HANDLE BAR	BENT	280.00	182.00
1	HANDLE BRACKET	NOT NECESSARY	250.00	-
1	STEERING CONE	NECESSARY	180.00	50.00
1	MIRROR	BROKEN	120.00	45.00
1	BRAKE LEVEL	CUT	80.00	80.00
1	IU UNIT	CUT	155.80	155.80
1	IU BRACKET	BENT	50.00	30.00
1	HEAD LAMP	CRACKED	150.00	150.00
1	HEAD LAMP STAY	TO REPAIR SEE LABOUR	180.00	-
1	INNER PANEL	CRACKED	180.00	110.00
1	PANEL COVER 1	CRACKED	150.00	120.00
1	PANEL COVER 2	CRACKED	120.00	120.00
1	SET DAY LIGHT	BROKEN	280.00	160.00
1	FRONT FAIRING RIGHT	CRACKED	200.00	145.00
1	FAIRING INNER COVER RIGHT	CRACKED	120.00	80.00
1	FRONT FAIRING LEFT	CRACKED	200.00	145.00
1	FAIRING INNER COVER LEFT	NOT NECESSARY	120.00	-
1	BODY UNDER COVER	NOT NECESSARY	150.00	-
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	180.00	-
1	FRONT FOOTREST BAR	BENT	250.00	115.00
1	FRONT FOOTREST RUBBER	TORN	100.00	30.00
1	HANDLE BALANCE	CUT	120.00	30.00

Report Ref No. CS/AGI22009621/Uvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BASKET	CRACKED	80.00	40.00
1	REAR FOOTREST LEFT	CUT	120.00	60.00
1	REAR FOOTREST BASKET LEFT	NOT NECESSARY	200.00	-
1	REAR MADGUARD	TORN	280.00	150.00
1	REAR FAIRING COVER	CUT	320.00	180.00
	LESS 10% DISCOUNT		-669.58	-
	LESS 20% DISCOUNT		-	-637.56
			6,026.22	2,550.24
1	FRONT NUMBER PLATE (SN)	NECESSARY	30.00	10.00
1	REAR BOX (SN)	CUT	450.00	220.00
1	REAR NUMBER PLATE (SN)	BENT	30.00	12.00
	LESS 10% DISCOUNT		-51.00	-
			459.00	242.00
	LABOUR			
	LABOUR. INCLUSIVE OF THE REPAIR OF HEAD LAMP STAY AND BRAKE PEDAL.		500.00	300.00
			500.00	300.00
GRAND TOTAL			6,985.22	3,092.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/AGI22009621/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.