

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009626/KWY3E2
Date: 17/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00007452201
Claimant Vehicle No :	SLQ1943R	Insured Vehicle No :	GBK9480G
Date of Loss:	04/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206621/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ1943R	Engine No:	4A92CP5440
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSRCY1AGU006903
Reg. Date:	30/06/2017 (Man. Year: 2017)	Odometer:	31801 km
Colour:	Metallic Blue		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,158.20	712.80	1,445.40	66.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	900.00	750.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,808.20	1,612.80	2,195.40	57.65
Approved Total (Overridden) (\$\$)		1,300.00		
Nett Amount (\$\$)	3,808.20	1,300.00	2,508.20	65.86

INSPECTION

Date of Assignment:	29/09/2022		
Date Inspected:	05/10/2022	Inspected At:	Spark Car Care @ Braddell (HQ) 205 BRADDELL RD Singapore 579701
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Feb 2023)
Parts:	143	mitsubishi LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ1943R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHF HEADLAMP	Cut	792.00 FL	*792.00 FL
2	1		*LHF FENDER	Repair	588.00 FL	*- FL
3	1		*FRONT BUMPER	Repair	858.00 FL	*- FL
4	15		*FRONT BUMPER CLIP	Not Necessary	90.00 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	22.00 FL	*- FL
6	8		*LHF FENDER CLIP	Not Necessary	48.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,398.00	792.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	239.80	79.20
Total Parts (\$\$)	2,158.20	712.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE ADMINSTRATIVE WORKS, APPLICATION AND RESEAL OFF-PICK CAR FRONT LICENCE PLATE	New	350.00	180.00
2	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE & REFIT DAMAGE PARTS	New	600.00	300.00
3	TO PUTTY & RESPRAY ON LHF FENDER, FRT BUMPER AND AFFECTED AREA	New	600.00	400.00
4	TO CHECK WIRING, FOCUS HEADLAMP	New	100.00	20.00
Gross Labour Cost (S\$)			1,650.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >