

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009628/UVY3Q2**Date:** 21/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00092942203	
<b>Claimant Vehicle No :</b>	SNE9950G	<b>Insured Vehicle No :</b>	SMK3129G	
Date of Loss:	28/09/2022	Nature of Claim:	TP	Claim No: SNM22D206938/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNE9950G</b>		Engine No:	LEB7258724
Make & Model:	HONDA FREED, 1.5 (A)		Chassis No:	GB73148993
Reg. Date:	26/04/2022 (Man. Year: 2021)		Odometer:	69864 km
Colour:	Blue			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Premio 7 mm	Rear Left Side:	Premio 7 mm
Front Right Side:	Premio 7 mm	Rear Right Side:	Premio 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,466.00	3,310.20	2,155.80	39.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	2,200.00	1,120.00	33.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>8,786.00</b>	<b>5,510.20</b>	<b>3,275.80</b>	<b>37.28</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	615.02	385.71	229.31	37.28
<b>Nett Amount (\$\$)</b>	<b>9,401.02</b>	<b>5,895.91</b>	<b>3,505.11</b>	<b>37.28</b>

**INSPECTION**

Date of Assignment:	29/09/2022	
Date Inspected:	06/12/2022	Inspected At: BW Workshop Services Pte Ltd (HQ) 291 Kaki Bukit Avenue 1, Shun Li Industrial Park Singapore 416080
Estimated Period of Repair:	6.0 days	

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2022)
<b>Parts:</b>	M1-MPV	HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNE9950G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,240.00 FL	*1,240.00 FL
2	1		*REAR TAILGATE TRIM BOARD	Deformed / Torn	355.00 FL	*355.00 FL
3	1		*REAR TAILGATE LOCK	Bent	185.00 FL	*185.00 FL
4	1		*REAR BUMPER	Dented / Deformed	822.00 FL	*822.00 FL
5	1		*REAR BUMPER SIDE RETAINER (LH)	Not Necessary	98.00 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER (RH)	Not Necessary	98.00 FL	*- FL
7	1		*REAR END PANEL	Badly Dented	540.00 FL	*540.00 FL
8	1		*REAR END PANEL INNER GARNISH	Twisted	192.00 FL	*192.00 FL
9	1		*WEATHERSTRIP	Twisted	190.00 FL	*190.00 FL
10	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
12	1		*H LOGO	Not Necessary	98.00 FS	*- FS
13	1		*HYBRID EMBLEM	Necessary	118.00 FS	*65.00 FS
14	1		*FREED EMBLEM	Necessary	98.00 FS	*60.00 FS
15	2		*REVERSE SENSOR	Shorted	500.00 FS	*200.00 FS
16	1		*POWER TAILGATE	Repair	1,200.00 FS	*- FS
17	1		*POWER TAILGATE FOOT SENSOR	Not Necessary	250.00 FS	*- FS
18	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
19	1		*REAR BUMPER SUPPORT (LH)	Bent	60.00 FL	*60.00 FL
20	1		*REAR BUMPER SUPPORT (RH)	Bent	60.00 FL	*60.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>6,234.00</b>	<b>4,039.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	768.00	728.80
<b>Total Parts (\$)</b>	<b>5,466.00</b>	<b>3,310.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIT AND TO RENEW AFFECTED PARTS	New	1,400.00	900.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	800.00	700.00
3	TO TRANSFER TAILGATE FITTINGS	New	120.00	60.00
4	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
5	TO REMOVE AND REFIT REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	150.00	50.00
6	TO REMOVE AND REFIT REVERSE CAMERA	New	150.00	40.00
7	TO FOCUS BOOT LAMPS .TO CHECK WIRING AND LIGHTING OPERATION	New	80.00	20.00
8	TO APPLY RUST PROOFING ON THE ADJUSTMENT PANELS	New	200.00	60.00
9	TO REPAIR POWER TAILGATE AND FOOT SENSOR	New	250.00	250.00
10	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	50.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,320.00</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >