

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22009629/UNY3Q2**Date:** 12/10/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : GBL1442P **Insured Vehicle No :** SNB3994K

Date of Loss: 24/09/2022 Nature of Claim: TP Claim No: DMPC2200439H.02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL1442P**

Make & Model: TOYOTA HIACE, 2.8 D (A) Engine No: 1GD8688506

Reg. Date: 19/03/2021 (Man. Year: 2021) Chassis No: GDH2011055635

Colour: Silver Odometer: 34793 km

Engine Capacity: 2754 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15

Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,351.40	5,805.67	5,545.73	48.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	2,280.00	550.00	19.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,181.40	8,085.67	6,095.73	42.98
Approved Total (Overridden) (S\$)		6,400.00		
Nett Amount (S\$)	14,181.40	6,400.00	7,781.40	54.87

INSPECTION

Date of Assignment: 29/09/2022

Date Inspected: 30/09/2022 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @
KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Oct 2022)	
Parts:	N/A	TOYOTA HIACE 2.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL1442P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,051.60 F	*2,051.60 FL
2	1		*REAR TAILGATE LOCK	Jammed	264.70 F	*264.70 FL
3	1		*REAR TAILGATE LOCK OUTER GARNISH	Cracked	137.60 F	*137.60 FL
4	1		*REAR TAILGATE WEATHERSTRIPE	Twisted	391.20 F	*361.20 FL
5	1		*REAR TAILGATE INNER TRIM BOARD	Torn	197.40 F	*197.40 FL
6	16		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	88.00 F	*- FL
7	1		*REAR TAILGATE NUMBER PLATE & BASE	Scratched	48.00 FS	*40.00 FS
8	1		*REAR TAILGATE NUMBER PLATE LAMP OUTER GARNISH	Cracked	346.50 F	*346.50 FL
9	2		*REAR TAILGATE NUMBER PLATE LAMP	Not Necessary	277.20 F	*- FL
10	1		*REAR TAILGATE INNER LOCK	Repeated	359.00 F	*- FL
11	1		*REAR TAILGATE HIACE EMBLEM	Necessary	105.00 F	*72.20 FL
12	1		*REAR TAILGATE TOYOTA LOGO MOTIF	Necessary	167.00 F	*68.50 FL
13	1		*REAR TAILGATE 70KM/H	Necessary	15.00 FS	*10.00 FS
14	1		*REAR TAILGATE 8PAX STICKER	Necessary	15.00 FS	*10.00 FS
15	1		*REAR TAILGATE WINDSCREEN MOULDING	No such part	219.00 F	*- FL
16	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
17	2		*REAR TAIL LAMP	Cracked	730.20 F	*730.20 FL
18	1		*REAR TAIL LAMP PANEL RH	Badly Dented	674.00 F	*408.20 FL
19	1		*REAR EXHAUST PIPE	Repair	971.10 F	*- FL
20	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	85.00 FS	*- FS
21	1		*REAR SPARE TYRE CARRIER	Bent	345.20 F	*345.20 FL
22	1		*REAR END PANEL INNER	Badly Dented	936.20 F	*801.00 FL
23	1		*REAR END PANEL OUTER	Badly Dented	566.10 F	*455.00 FL
24	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
25	1		*REAR BUMPER	Distorted	599.30 F	*599.30 FL
26	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*40.00 FS
27	4		*REAR BUMPER BRACKETS	Bent	404.00 F	*120.00 FL
28	1		*REAR BUMPER REVERSE SENSOR	Torn	220.00 FS	*200.00 FS
29	1		*REAR BUMPER STEP PANEL	Bent	262.30 F	*262.30 FL
30	1		*REAR FLOOR PANEL BEAM	Repair	277.80 F	*- FL
31	1		*REAR FLOOR PANEL TOP WOODEN BOARD	Serviceable	450.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,351.40	7,610.90
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,805.23
Total Parts (\$)	11,351.40	5,805.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	20.00
2	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	120.00	60.00
3	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	120.00
4	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	80.00	40.00
5	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	150.00	60.00
6	LABOR FOR PANEL BEATING ,CUT ,WELD STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	1,000.00
7	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,000.00	900.00
8	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	80.00
Gross Labour Cost (\$\$)			2,830.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >