



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD c/o SEDGWICK SINGAPORE PTE LTD 30 CECIL STREET, LEVEL 12 PRUDENTIAL TOWER SINGAPORE 049712			Ref: CS/SGK22009633/Tqy3m4 Date: 24/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	UNKNOWN	Veh. Inspected	FS72HSA20006	
Policy No.	SGK: 6013206/ARI	Coverage (\$)	0.00	
Claim No.	D22000299FAIR	Excess (\$)	0.00	
Assign From	ABRAHAM RAJADURAI	Assign Date	29/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	FS72HSA20006	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	9 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	9 mm	
R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	9/9 mm	
L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	9/9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/07/2022	Inspection Date	30/09/2022	
Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	