

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22009636/ANCE2**Date:** 01/03/2023**REFERENCE**

Insured/Claimant: ANG HUILING (HONG HUILING)

Policy No: 7210053172

Date of Loss: 22/09/2022

Nature of Claim: OD

Claim No: 6348951669SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKN2571B**Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17)
(A)

Engine No: CZDC37045

Reg. Date: 27/05/2021 (Man. Year: 2021)

Chassis No: WAUZZZF37M1100354

Colour: White

Odometer: 4163 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$150,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R17

Rear Tyre Size: 215/65 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,439.00	8,931.92	6,507.08	42.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,632.00	11,807.00	8,825.00	42.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,071.00	20,738.92	15,332.08	42.51
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	35,271.00	19,938.92	15,332.08	43.47
+ GST 8.00/8.00% (S\$)	2,821.68	1,595.11	1,226.57	43.47
Nett Amount (S\$)	38,092.68	21,534.03	16,558.65	43.47

INSPECTION

Date of Assignment: 30/09/2022

Date Inspected: 28/09/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,738.00 FS	*- FS
2	1		*REAR BUMPER SPOILER	Not Necessary	510.00 FS	*- FS
3	1		*REAR BUMPER ADAPTER - LH	Not Necessary	95.00 FS	*- FS
4	1		*REAR UNDERBODY TRIM - LH	Not Necessary	63.00 FS	*- FS
5	1		*REAR FENDER - LH	Dented	3,899.00 FS	*3,119.20 FS
6	1		*REAR SIDE WINDOW - LH	Necessary	683.00 FS	*546.40 FS
7	1		*REAR WHEEL SPOILER - LH	Not Necessary	44.00 FS	*- FS
8	1		*REAR SIDE MEMBER TRIM - LH	Not Necessary	189.00 FS	*- FS
9	1		*REAR DOOR - LH	Dented	3,028.00 FS	*2,422.40 FS
10	1		*REAR OUTER DOOR SEAL - LH	Necessary	151.00 FS	*120.40 FS
11	1		*REAR DOOR CATCH - LH	Damaged	134.00 FS	*106.80 FS
12	1		*REAR SILL PANEL SEAL - LH	Not Necessary	151.00 FS	*- FS
13	1		*REAR DOOR COVER - LH	Cut	368.00 FS	*294.00 FS
14	1		*REAR DOOR HANDLE - LH	Repair	223.00 FS	*- FS
15	1		*REAR DOOR HANDLE HOUSING - LH	Repair	31.00 FS	*- FS
16	1		*REAR DOOR HANDLE MOUNTING NAR - LH	Not Necessary	182.00 FS	*- FS
17	1		*REAR DOOR HANDLE BOWDEN CABLE - LH	Not Necessary	58.00 FS	*- FS
18	1		*REAR WINDOW REGULATOR - LH	Not Necessary	302.00 FS	*- FS
19	1		*REAR WINDOW REGULATOR MOTOR - LH	Not Necessary	300.00 FS	*- FS
20	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	262.00 FS	*- FS
21	2		*REAR WHEEL COVER - LH / RH	N/S Missing / O/S Necessary	1,132.00 FS	*904.80 FS
22	1		*REAR CROSS PANEL - LH	Not Necessary	445.00 FS	*355.60 FS
23	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
25	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
26	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
27	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
28	1		*LHS REAR TYRE (NPA)	Not Necessary	0.00 FS	*- FS
29	1		*SUNDRIES	Necessary	500.00 FS	*182.32 FS
30	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	71.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,439.00 8,931.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	300.00	300.00
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	400.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
6	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
7	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED	New	8,000.00	3,500.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR COVER, DOOR HANDLE, ROOF CHANNEL, LHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS	New	7,500.00	3,575.00
10	TO RENEW LHS REAR TYRE AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
Gross Labour Cost (\$\$)			20,632.00	11,807.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >