



Your Ref: S1M03GP4

Date: 16<sup>th</sup> Dec 2022

Our Ref: CS3/ASM21009458/Gny3e2-1

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Ang Yvonne

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBJ 3326P**

**INSURED VEHICLE: SHC 7061S**

**ACCIDENT DATE: 27/08/2021**

We thank you for your instruction on 28/09/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBJ 3326P from M/s Prudent Adjustors Services.
- b) Singapore Accident Statement of Vehicles FBJ 3326P and SHC 7061S.
- c) Police Report of Vehicle FBJ 3326P.
- d) Colour damaged vehicle photographs of FBJ 3326P.

Pre-Repair Inspection Date: 08/09/2021 at M/s He Xin Motor, 25 Kaki Bukit Road 4 #01-75 Synergy @ KB, Singapore 417800.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

|                      |                       |
|----------------------|-----------------------|
| Registration Number  | : FBJ 3326P           |
| Make & Model         | : Yamaha Tmax 530 Cvt |
| Year of Registration | : 2014                |
| Chassis Number       | : JYASJ091000018587   |
| Engine Capacity      | : 530 cc              |

- 2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.