



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 1095A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	R/H HANDLER END	CUT	65.00	65.00
1	TOP COWLING	CUT	650.00	450.00
1	R/H SIGNAL LIGHT	CRACKED	98.00	98.00
1	LOW COWLING	CUT	380.00	280.00
1	MUFFLER ASSY	CRACKED	1,180.00	980.00
1	FORK ASSY	BENT	980.00	680.00
1	UNDER BRACKET	BENT	480.00	280.00
1	STEERING CON	NECESSARY	180.00	120.00
1	WINDSHIELD	CRACKED	285.00	250.00
1	METER PANEL COVER	NOT NECESSARY	135.00	-
1	REAR BOX	CUT	485.00	400.00
1	SET SPARY COVER	DISTORTED	800.00	500.00
	LESS 10% DISCOUNT		-	-410.30
			5,718.00	3,692.70
	<u>LABOUR</u>			
	TSP.	NOT NECESSARY	100.00	-
	LABOUR.		500.00	300.00
			600.00	300.00
	GRAND TOTAL		6,318.00	3,992.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CS/SMR22009638/Tqy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.