

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 7244G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DISTORTED	481.10	481.10
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	CRACKED	171.45	171.45
1	REAR BUMPER SIDE ATTACHMENT LH (CONSISTENT)	CRACKED	181.10	181.10
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	SCRATCHED	231.75	85.10
1	SET REAR BUMPER CLIP (CONSISTENT)	NECESSARY	103.20	50.00
1	REAR BUMPER DUST COVER LH (CONSISTENT)	TORN	181.10	181.10
3	REAR BUMPER DUST COVER CLIPS @\$12.90 (CONSISTENT)	NOT NECESSARY	38.70	-
1	TAIL LAMP LH (CONSISTENT)	CRACKED	571.75	571.75
1	TAIL LAMP SEALANT (CONSISTENT)	NOT NECESSARY	50.00	-
2	TAIL LAMP CLIPS @\$12.90 (CONSISTENT)	NOT NECESSARY	25.80	-
	LESS 25% DISCOUNT		-508.99	-430.40
			1,526.96	1,291.20
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (CONSISTENT) (SN)	NOT NECESSARY	380.00	-
			380.00	-
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		40.00	20.00
	TO TUFF COAT AFFECTED AREAS.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIX REVERSE SENSOR.		120.00	50.00
	TO RESPRAY AFFECTED AREAS.		800.00	600.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR REAR LH FENDER, REAR END PANEL & ALIGNED ALL PARTS.		800.00	550.00
			1,880.00	1,220.00
	GRAND TOTAL		3,786.96	2,511.20

Report Ref No. CS/ASM22009639/Ucy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,000.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/ASM22009639/Ucy3m4

CHUA KANG SENG
Licensed Appraiser