Adjuster Report 11/8/22, 11:33 AM

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22009640/ENY3E2

08/11/2022 Date:

**REFERENCE** 

Handling Insurer: **ECICS Limited** 

Policy No:

**Claimant Vehicle** No:

SCH3132E

Insured Vehicle No:

**GBL2795P** 

Date of Loss:

Reg. Date:

20/09/2022

Nature of Claim:

TP

Claim No:

DMCV2200003H/ST

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SCH3132E** Reg No:

Make & Model: SUBARU FORESTER, 2.5 (A)

16/05/2016 (Man. Year: 2016)

Engine No: Chassis No: Odometer:

FA20A929987 JF1SJGK85GG072024

51059 km

Colour: White

**Engine Capacity:** 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R15 Rear Tyre Size: 215/60 R15 Front Left Side: Rear Left Side: Dunlop 4 mm Dunlop 4 mm Rear Right Side: Front Right Side: Dunlop 4 mm Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		836.96	498.08	338.88	40.49
Miscellaneous Items		0.00	0.00	0.00	
Labour		6,240.00	2,610.00	3,630.00	58.17
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	7,076.96	3,108.08	3,968.88	56.08
	+ GST 7.00/7.00% (S\$)	495.39	217.57	277.82	56.08
	Nett Amount (S\$)	7,572.35	3,325.65	4,246.70	56.08

**INSPECTION** 

Date Inspected:

Date of Assignment: 30/09/2022

> Motor Image Enterprises Pte Ltd (Leng Kee) 03/10/2022 Inspected At:

25 Leng Kee Road

Singapore 159097

Estimated Period of Repair: 3.0 days

HUEY YON Adjuster: **CHEN TSUE YEE** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2022)

Parts: M1-SUV SUBARU FORESTER 2.5 (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SCH3132E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FACE R	Dented	555.00 FN	*555.00 FN
2	1		*BRKT SD R RH	Necessary	14.80 FN	*14.80 FN
3	1		*BRKT SD R LH	Necessary	14.80 FN	*14.80 FN
4	1		*BEAM COMPL R EU	Repair	296.00 FN	*- FN
5	1		*COVER HOOK R	Crushed	13.00 FN	*13.00 FN
6	9		*CLIP BMPR	Not Necessary	21.60 FN	*- FN
7	2		*CLIP	Not Necessary	6.00 FN	*- FN
8	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
F=Fra	anchise	part. S=SpcNett.	N=NettItemDisc.	-		
				Sub Total (S\$)	1,021.20	617.60
			- Nett Item Disc	count on N Items 20.00/20.00% (S\$)	184.24	119.52
				Total Parts (S\$)	836.96	498.08

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
REPLACE REAR BUMPER ,BUMPER BEAM AND REPAIR END PANEL	New	1,860.00	600.00
RESPRAY REAR BUMPER, BUMPER BEAM, END PANEL AND TAILGATE	New	2,080.00	520.00
TO SUPPLY & INSTALL REVERSE SENSOR	New	300.00	80.00
APPLY SEALANT TO AFFECTED AREA	New	200.00	0.00
TO CONDUCT WATER SEEPAGE TEST	New	100.00	0.00
TO CONDUCT (REAR) ANTI RUST COATING	New	580.00	290.00
REPAIR REAR END PANEL AND BUMPER BEAM	New	600.00	600.00
RESPRAY REAR END PANEL AND BUMPER BEAM	New	520.00	520.00
Gross Labour Cost (S\$		6,240.00	2,610.00
	OUR Items  REPLACE REAR BUMPER ,BUMPER BEAM AND REPAIR END PANEL RESPRAY REAR BUMPER ,BUMPER BEAM ,END PANEL AND TAILGATE TO SUPPLY & INSTALL REVERSE SENSOR APPLY SEALANT TO AFFECTED AREA TO CONDUCT WATER SEEPAGE TEST TO CONDUCT (REAR) ANTI RUST COATING REPAIR REAR END PANEL AND BUMPER BEAM RESPRAY REAR END PANEL AND BUMPER BEAM	REPLACE REAR BUMPER ,BUMPER BEAM AND REPAIR END PANEL New RESPRAY REAR BUMPER ,BUMPER BEAM ,END PANEL AND TAILGATE New TO SUPPLY & INSTALL REVERSE SENSOR New APPLY SEALANT TO AFFECTED AREA New TO CONDUCT WATER SEEPAGE TEST New TO CONDUCT (REAR) ANTI RUST COATING New REPAIR REAR END PANEL AND BUMPER BEAM New	REPLACE REAR BUMPER ,BUMPER BEAM AND REPAIR END PANEL RESPRAY REAR BUMPER ,BUMPER BEAM ,END PANEL AND TAILGATE New 2,080.00 TO SUPPLY & INSTALL REVERSE SENSOR APPLY SEALANT TO AFFECTED AREA New 200.00 TO CONDUCT WATER SEEPAGE TEST New 100.00 TO CONDUCT (REAR) ANTI RUST COATING REPAIR REAR END PANEL AND BUMPER BEAM New 580.00 RESPRAY REAR END PANEL AND BUMPER BEAM New 520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >