

OH APPRAISAL SERVICES

BLK 34,#02-309,TOA PAYOH,LORONG 5

SINGAPORE (310034)

Mobile : 97982959 Fax : 63975857 email : oh3434@yahoo.com.sg

Business Regn No 53214975X

VEHICLE DAMAGE INSPECTION REPORT

Mr. Ng Boon Fann
Blk 3 Punggol Field Walk
#04-05
Singapore 828740

Our Ref :FBG4197D/TP5012
Date : 14 March 2022

REFERENCES

Claim Type	: Third Party	Date of Accident	: 02 December 2021
Vehicle No.	: FBG4197D	Date of Assignment	: 20 December 2021
Make	: Yamaha	Date of Inspection	: 20 December 2021
Model	: Jupiter MX 135	Date of Re-inspn.	: 08 January 2022
Reg. Date	: 2014	Chassis No	: MH350C002CK365084
Color	: Black	Engine No	: Blocked
Odometer	: 69809 km		

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
<u>Front</u>	Diamond	70-90/17	3
<u>Rear</u>	Diamond	100/80-17	4

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

Front and Both side portion

Remark: Owner confirm with Legal Option LLC that he will renew COE (FBG4197D)

INSPECTION AND ADJUSTMENT

Original Quotation	: <u>\$4,013.00</u>	Revised	<u>\$2,200.00</u>
		Assessment	<u>Lump sum</u>

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
(5) days to complete.(Survey at All Wheel Motoring.)

This survey was conducted on a "WITHOUT PREJUDICE" basis.

S/N	Description	Qty	Condition	Original Quotation	Revised Quotation	
1	Handle bar front cover	1 pc	Grazed	95.00	95.00	
2	Handle bar rear cover	1 pc	Usable	75.00	0.00	Xnn
3	Handle bar	1 pc	Bent	65.00	65.00	Xnn.
4	Handle bar bracket @\$28/-	2 pcs	Distorted	56.00	56.00	Xnn.
5	Handle balancer @\$22/-	2 pcs	Grazed	44.00	44.00	
6	Handle grip	1 set	Cut	32.00	32.00	
7	Brake lever	1 pc	Bent	28.00	28.00	
8	Clutch lever	1 pc	Bent	28.00	28.00	
9	Mirror @\$35/-	2 pcs	Cracked/grazed	70.00	70.00	
10	Front cowling	1 pc	Grazed	125.00	125.00	
11	Head lamp	1 pc	Grazed/cut	105.00	105.00	
12	Headlamp bracket	1 pc	Bent	48.00	48.00	
13	Front signal @ \$38/-	2 pcs	Grazed	76.00	76.00	
14	Front mudguard	1 pc	Cracked	60.00	60.00	
15	Front fork assy @ \$350/-	2 pcs	Align	700.00	S.N.200.00	SN120
16	Front fork under bracket	1 pc	Distorted	220.00	220.00	Xnn.
17	Front disc plate	1 pc	Usable	135.00	0.00	Xnn
18	Side fairing @\$108/-	2 pcs	Cracked/grazed	216.00	216.00	
19	Side fairing panel @\$40/-	2 pcs	Grazed/Cut	80.00	80.00	
20	Chassis frame cover (Front)	1 pc	Deformed	65.00	65.00	Xnn
21	Chassis frame cover (Rear)	1 pc	Grazed	45.00	45.00	Xnn
22	Front foot rest bar	1 pc	Bent	40.00	40.00	
23	Front foot rest rubber	1 set	Cut	16.00	16.00	
24	Brake pedal	1 pc	Bent	32.00	32.00	
25	Side stand	1 pc	Bent	35.00	35.00	
26	Rear footrest Rh	1 pc	Bent	30.00	30.00	
27	Rear footrest bracket Rh	1 pc	Bent	55.00	55.00	
28	Tail board @\$85/-	1 pc	Cut Rh	170.00	85.00	
29	Exhaust protector (Front)	1 pc	Bent	55.00	55.00	
30	Exhaust protector (Rear)	1 pc	Dented	75.00	75.00	
31	Exhaust assy	1 pc	Dented	295.00	295.00	
Less 0% & 10% discount				3171.00	2176.00	1725
				0.00	217.60	1552.50
				3171.00	1958.40	SN120
Add special nett from above					200.00	
35	Front number plate	1 pc	Bent	12.00	10.00	✓
36	Steering cone & bearing	1 pc	Necessary 50%	55.00	27.50	✓ 72.5
40	Centre basket	1 pc	Grazed	35.00	35.00	✓
Towing fee (Two ways)				60.00	50.00	✓
Rim alignment				100.00	60.00	40
Check electrial				80.00	60.00	30
Labour charges				500.00	400.00	200.
				4013.00	2800.90	320
Lump sum repair adjustment					2200.00	

1552.50

120

72.50

420

2065

4591650 104 days

OH APPRAISAL SERVICES

Vehicle No: FBG4197D

Our Ref : FBG4197D/TP5012

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.



For Oh Appraisal Services