

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21012713/T1qy3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER 04/01/2022 Date: SINGAPORE 068811 ATTN: CHEN XINYOU Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHD 7261B FBG 4197D Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03NPZ Excess (\$) 0.00 **CHEN XINYOU Assign Date** 15/12/2021 Assign From **Vehicle Particulars & Condition** 2. YAMAHA JUPITER MX Make & Model 134 C.C HIDDEN 2012 Engine No. Year of Reg. MH350C002CK365084 **BLACK** Chassis No. Colour Odometer Steering **IN ORDER** IN ORDER NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 70/90 R17 MAXXIS 5 mm L/H Front Tyre mm 100/80 R17 **MAXXIS** R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S, O/S BODY AND FRONT PORTION. 5. **General Information** 02/12/2021 17/12/2021 (02:00 PM) Inspect Date / Time Accident Date 5032 Ang Mo Kio Industrial Park 2, #01-307, Survey held at Repairer ALL WHEEL MOTORING 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500

Report Ref No. CS3/ASM21012713/T1qy3e2

Estimate Days of Repair

Inspected By

5b.

MOHAMAD TAUFIKH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

5 Working Days

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser