

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No: 199607198R GST Reg. No. 19-9607198-R | | | | |
|---|--|---|-----------------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | Ref: | CS/AGI22009645/Avy3e2 | |
| | | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | Date: | 20/02/2023 | |
| | | | Code | AGI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SMF 1654X | Veh. Inspected | SGL 6918S | |
| | Policy No. | P10453958R01 | Coverage (\$) | 0.00 | |
| | Claim No. | C10017692 | Excess (\$) | 0.00 | |
| | Assign From | MAYBIE CHUA | Assign Date | 30/09/2022 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | MAZDA 6 | C.C | 1998 | |
| | Engine No. | HIDDEN | Year of Reg. | 2015 | |
| | Chassis No. | JM6GJ1072G0222060 | Colour | BRONZE | |
| | Odometer | 163526 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 225/55 R17 | GOODYEAR | 6 mm | |
| | L/H Front Tyre | 225/55 R17 | GOODYEAR | 6 mm | |
| | R/H Rear Tyre | 225/55 R17 | GOODYEAR | 6 mm | |
| | L/H Rear Tyre | 225/55 R17 | GOODYEAR | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 23/09/2022 | Inspection Date | 03/10/2022 | |
| | Survey held at 1ST AUTOWORKS PTE LTD | | | | |
| | | 23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933 | | | |
| 5a. | | Remarks | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: