

AUTO PERFORMANCE APPRAISAL

APA

TAX INVOICE

HM LIMO Pte Ltd
C/O T & S Motor Service
Blk 5035 Ang Mo Kio Industrial Park 2
#01-357
Singapore 569538

INVOICE NO : APA22002402

DATE : 02/07/2022

VEHICLE NO : SLH8740K

JOB REFERENCE NO : 22/002519

ACCIDENT DATE : 18/06/2022

SURVEY DATE : 21/06/2022

<u>DESCRIPTION</u>	<u>AMOUNT</u>
Survey Fees Inclusive Of Transportation	\$725.00
Photographs (\$1) Per Copies : 98	\$122.00

TOTAL AMOUNT : \$847.00

Notes :

All cheque payment should be "Crossed" and made payable to "Auto Performance Appraisal"

Auto Performance Appraisal



AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																															
<p>HM LIMO Pte Ltd C/O T & S Motor Service Blk 5035 Ang Mo Kio Industrial Park 2 #01-357 Singapore 569538</p>																															
1	Reference Job Reference No : 22/002519 Claim No : - Claim Type : Third Party Accident Date : 18/06/2022 Survey Date : 21/06/2022 Survey Report Date : 02/07/2022																														
2	Particulars Of Vehicle Vehicle Registration No : SLH8740K Make & Model : Toyota Prius Hybrid 1.8 CVT Vehicle Registration Date : 22/11/2016 Chassis No : JTDKB3FU003538145 Engine No : Blocked Colour : Silver																														
3	Condition Of Vehicle And Tyres <table border="1"><thead><tr><th><u>Mileage (KM)</u></th><th><u>Brakes</u></th><th><u>Steering</u></th><th><u>Modification</u></th></tr></thead><tbody><tr><td>256031</td><td>Serviceable</td><td>Serviceable</td><td>None</td></tr><tr><td><u>Tyres</u></td><td><u>Make</u></td><td><u>Size</u></td><td><u>Balance (MM)</u></td></tr><tr><td>Front RHS</td><td>CST</td><td>195/65R15</td><td>5</td></tr><tr><td>Front LHS</td><td>CST</td><td>195/65R15</td><td>5</td></tr><tr><td>Rear RHS</td><td>CST</td><td>195/65R15</td><td>6</td></tr><tr><td>Rear LHS</td><td>CST</td><td>195/65R15</td><td>6</td></tr></tbody></table>			<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	256031	Serviceable	Serviceable	None	<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	CST	195/65R15	5	Front LHS	CST	195/65R15	5	Rear RHS	CST	195/65R15	6	Rear LHS	CST	195/65R15	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																												
256031	Serviceable	Serviceable	None																												
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																												
Front RHS	CST	195/65R15	5																												
Front LHS	CST	195/65R15	5																												
Rear RHS	CST	195/65R15	6																												
Rear LHS	CST	195/65R15	6																												
4	Description Of Damages The vehicle sustained damages at frontal and rear portion. (For information of damages please refer to Parts/Labour/Photographs attached)																														
5	Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																														

AUTO PERFORMANCE APPRAISAL

Annex A1

Vehicle Assessment Reports

Ref No : 22/002519

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
List Items					
1	1	Front bumper	Dented/broken	526.00	526.00
2	1	Front bumper centre "TOYOTA"	Cut/necessary	92.00	92.00
3	1	Front bumper number plate garnish	Deformed/torn	89.60	89.60
4	2	Front bumper side fog lamp	Serviceable/reuse	961.70	-
5	1	Front bumper inner top grille	Deformed	220.40	220.40
6	1	Front bumper lower grille	Deformed	319.70	349.70
7	2	Front bumper side retainer	Deformed	161.40	161.40
8	1	Front bumper inner lower reinforcement	Serviceable/reuse	336.30	-
9	1	Front bumper inner foam	Torn	87.00	87.00
10	1	Front bumper inner top	Dented/bent	772.60	772.60
11	1 set	Front bumper clips	Broken/necessary	50.00	50.00
12	2	Headlamp	Broken/cut	5,323.40	5,323.40
13	1	Front support panel	To repair	426.00	-
14	1	Rear bumper	Deformed/dented	485.60	485.60
15	2	Rear bumper side lamp	Bent/cut	1,004.00	1,004.00
16	1	Rear bumper lower black spoiler	Deformed/cut	576.30	576.30
17	1	Rear bumper lower centre black spoiler RH tow cover	Deformed	15.60	15.60
18	2	Rear bumper side retainer	Deformed	233.00	233.00
19	1	Rear bumper inner reinforcement	Dented/bent	400.30	400.30
20		Rear bumper inner reinforcement lower cover	Broken/deformed	112.40	112.40
21	1 set	Rear bumper clips	Broken/necessary	40.00	40.00
22	1	Rear tailgate	Badly dented/bent	1,147.80	1,147.80
23	1	Rear tailgate outer cover	Broken/dented	925.40	925.40
24	1	Rear tailgate centre "TOYOTA" logo	Necessary	47.90	47.90
25	1	Rear tailgate RH "HYBRID" emblem	Necessary	54.60	54.60
26	1	Rear tailgate LH "PRIUS" emblem	Necessary	54.80	54.80
27	2	Rear number plate lamp	Serviceable/reuse	252.00	-
28	1	Rear tailgate inner top trim board	Serviceable/reuse	259.20	-
29	1 set	Rear tailgate inner trim board clips	Necessary	60.00	60.00
30	1	Rear tailgate top lock	Bent	467.00	467.00
31	1	Rear tailgate weatherstrip	Deformed/cut	372.30	372.30
32	2	Taillamp	Broken/cut	903.80	903.80
33	1	Rear end panel	Buckled	651.00	651.00
34	1	Rear end panel top garnish	Deformed/broken	126.70	126.70
35	1	Rear end panel keyless sensor	Malfunction	73.00	73.00
36	2	Rear corner panel	RH buckled/LH repair	484.00	242.00

AUTO PERFORMANCE APPRAISAL

Annex A2

Vehicle Assessment Reports

37	2	Rear fender under splash shield	RH deformed/LH reuse	252.00	126.00
38	1 set	Rear fender under splash shield	Broken/necessary	40.00	40.00
				18,404.80	15,831.60
Less discount 25%				4,601.20	3,957.90
Total :				13,803.60	11,873.70

Special Nett Items

39	1	Front number plate	Dented/bent	45.00	45.00
40	1 set	Rear bumper reverse sensors	Malfunction	250.00	250.00
41	1	Rear number plate	Dented/bent	45.00	45.00
42	1 set	Rear reverse camera	Malfunction	450.00	450.00
43	1 set	Rear windscreen sealant	Necessary	50.00	50.00
44	1 set	Rear end panel sealant	Necessary	50.00	50.00
Total :				890.00	890.00

Total Spare Parts :	14,693.60	12,763.70
---------------------	-----------	-----------

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 22/002519

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,500.00	1,100.00
2	To putty and respray painting on affected areas.	2,000.00	1,600.00
3	To remove, refix rear windscreen glass.	140.00	120.00
4	To check wirings and lightings front & rear portion.	80.00	50.00
5	To remove, refix reverse sensors and reverse camera.	140.00	100.00
6	To remove, refix rear upholstery and attachments.	120.00	80.00
7	To remove, refix tailgate fittings to facilitate repair.	80.00	60.00
8	To supplied and applied anti rust treatments.	120.00	80.00
Total Labour :		4,180.00	3,190.00
Total Spare Parts :		14,693.60	12,763.70
Total Labour :		4,180.00	3,190.00
Total Repair Costs :		18,873.60	15,953.70

Assessor's Recommendation

Repairer Estimate : 18,873.60
Our Adjustment : 15,953.70

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$12,750.00, with a repair period of 9 working days.

Surveyed By:



Lek Boon Hwee
Automobile Appraiser