

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22009652/Kcy3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811			Date:	11/10/2022	
	ATTN: OH VALE			Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 3960J	Veh. Inspected	k	SMD 8924G	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M04BY0	Excess (\$)		0.00	
	Assign From	OH VALE	Assign Date		29/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI LANCER (A)	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	JMYSTCY4A8U004758	Colour		WHITE	
	Odometer	210353 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55Z R17	NEXEN		7 mm	
	L/H Front Tyre	205/55Z R17	NEXEN		7 mm	
	R/H Rear Tyre	205/55Z R17	NEXEN		8 mm	
	L/H Rear Tyre	205/55Z R17	NEXEN		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
5.	General Information					
	Accident Date	27/09/2022	Inspect Date /	Time	30/09/2022 (02:00 PM)	
	Survey held at ASTUTE AUTOWORKS PTE LTD					
	60 JALAN LAM HUAT, #02-16/17, CARROS CENTRE SINGAPORE 737869					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/ASM22009652/Kcy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser