

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009653/TQY3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00147002104

Claimant Vehicle No : SLU4255C **Insured Vehicle No :** GBG9324X

Date of Loss: 27/09/2022 Nature of Claim: TP Claim No: SNM22D206919/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU4255C**

Make & Model: SUBARU IMPREZA 4D, 1.6 I-S AWD CVT (A) Engine No: FB16YB10548

Reg. Date: 01/11/2017 (Man. Year: 2017) Chassis No: JF1GK3KC5HG004901

Colour: Blue Odometer: 81165 km

Engine Capacity: 1600 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/50 R17 Rear Tyre Size: 205/50 R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,728.04	6,204.04	524.00	7.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,935.00	10,165.00	1,770.00	14.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,663.04	16,369.04	2,294.00	12.29
+ GST 7.00/7.00% (S\$)	1,306.41	1,145.83	160.58	12.29
Nett Amount (S\$)	19,969.45	17,514.87	2,454.58	12.29

INSPECTION

Date of Assignment: 30/09/2022

Date Inspected: 30/09/2022 Inspected At: Motor Image Enterprises Pte Ltd (Leng Kee)
25 Leng Kee Road
Singapore 159097

Estimated Period of Repair: 13.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2023)
Parts:	143	SUBARU IMPREZA 4D 1.6 I-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU4255C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PNL SD OUT QTR RRH	Buckled	973.10 FN	*973.10 FN
2	1		*R FLOOR PANEL 4D	Not Necessary	444.00 FN	*- FN
3	1		*SKIRT COMPL R 4D	Deformed	272.70 FN	*272.70 FN
4	1		*TRUNK LID COMPL	Bent	624.00 FN	*624.00 FN
5	1		*HINGE TRUNK RH	Bent	74.00 FN	*74.00 FN
6	1		*HINGE TRUNK LH	Bent	74.00 FN	*74.00 FN
7	1		*WSTR TRUNK	Not Necessary	92.50 FN	*- FN
8	1		*BUMPER FACE R 4D FHI	Deformed	466.20 FN	*466.20 FN
9	1		*BRKT SD R 4D FHI RH	Deformed	31.50 FN	*31.50 FN
10	1		*BRKT SD R 4D FHI LH	Deformed	31.50 FN	*31.50 FN
11	1		*BRKT CORNER R 4D RH	Deformed	18.50 FN	*18.50 FN
12	1		*BRKT CORNER R 4D LH	Deformed	18.50 FN	*18.50 FN
13	1		*BEAM COMPL R EU	Bent	208.60 FN	*208.60 FN
14	1		*COVER HOOK R 4D FHI	Deformed	9.30 FN	*9.30 FN
15	1		*WINDOW GL ASSY R EXP	Necessary	2,016.50 FN	*2,016.50 FN
16	1		*DAM RUBBER LWR FHI	Necessary	8.50 FN	*8.50 FN
17	1		*MOLDING R FHI	Necessary	40.00 FN	*40.00 FN
18	1		*LENS & BODY COMPL	Cut	37.00 FN	*18.50 FN
19	1		*LENS & BODY COMPLRH	Cracked	388.50 FN	*388.50 FN
20	1		*LENS & BODY COMPLLH	Cracked	388.50 FN	*388.50 FN
21	1		*LENS & BODY COMPLLH	Cut	207.20 FN	*207.20 FN
22	1		*LENS & BODY COMPLRH	Cut	207.20 FN	*207.20 FN
23	1		*PACKING LH	Necessary	18.50 FN	*18.50 FN
24	1		*PACKING RH	Necessary	18.50 FN	*18.50 FN
25	1		*PACKING LH	Necessary	18.50 FN	*18.50 FN
26	2		*CLIP	Necessary	6.00 FN	*6.00 FN
27	1		*ORNAMENT ASSY F SIX	Necessary	74.00 FN	*74.00 FN
28	1		*LETTER MK R	Necessary	81.40 FN	*81.40 FN
29	1		*LETTER MK R IMP	Necessary	37.00 FN	*37.00 FN
30	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
31	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
32	1		*EXH PIPE ASSY R SIS	Bent	506.90 FN	*506.90 FN
33	1		*MUFFLER ASSY RH	Bent	518.00 FN	*518.00 FN
34	1		*TAIL PIPE CUTTER	Bent	74.00 FN	*74.00 FN
35	1		*QTR PNL R END CPLRH	Bent	62.90 FN	*62.90 FN
36	1		*LOCK AY TRUNK	Bent	162.80 FN	*162.80 FN
37	1		*PACKING RH	Distorted	18.50 FN	*18.50 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	8,373.80	7,738.80
- Nett Item Discount on N Items 20.00/20.00% (S\$)	1,645.76	1,534.76
Total Parts (S\$)	6,728.04	6,204.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER ,BUMPER BEAM ,REAR BOOTLID ,END PANEL ,SPARE TYRE PANEL & REAR RH QUARTER PANEL	New	3,720.00	3,000.00
2	RESPRAY REAR BUMPER ,REAR BOOTLID ,BUMPER BEAM ,END PANEL ,SPARE TYRE PANEL	New	2,700.00	2,080.00
3	TRANSFER (BOOTLID) MECHANISM	New	200.00	150.00
4	REMOVE & REFIX CARPET ,SEATS TO FACILITATE REPAIRS	New	400.00	400.00
5	APPLY SEALANT TO EFFECTED AREA	New	200.00	200.00
6	TO SUPPLY & INSTALL REVERSE SENSOR	New	400.00	400.00
7	CONDUCT (REAR)LIGHTING TEST	New	50.00	50.00
8	CONDUCT (REAR BOOTLID)WATER LEAK TEST	New	50.00	50.00
9	FAULT DIAGNOSTIC (RESET)	New	280.00	280.00
10	REMOVE & INSTALL REAR WINDSCREEN	New	300.00	300.00
11	TO SUPPLY & INSTALL (REAR) WINDSCREEN TINTED FILM	New	145.00	145.00
12	CONDUCT (REAR) ANTI-RUST COATING	New	580.00	580.00
13	REMOVE & REPLACE EXHAUST MUFFLER AND CENTRE PIPE	New	150.00	150.00
14	REPAIR REAR SPARE TYRE PANEL	New	600.00	560.00
15	REPLACE REAR END PANEL	New	600.00	560.00
16	RESPRAY REAR QUARTER PANEL LH ,QUARTER PANEL RH AND SPARE TYRE PANEL	New	1,560.00	1,260.00
Gross Labour Cost (S\$)			11,935.00	10,165.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >