



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 6456G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED / SCRAPED / TORN	843.00	633.00
2	FRONT BUMPER SIDE RETAINER	NECESSARY	63.00	63.00
10	FRONT BUMPER RETAINING CLIP	NOT NECESSARY	60.00	-
1	FRONT BUMPER DAYTIME RUNNING LAMP RH	LEG BENT / FRACTURED	225.00	225.00
1	DAYTIME RUNNING LAMP TRIM MOULDING RH	BROKEN	108.00	108.00
1	FRONT BUMPER SPONGE	BROKEN	110.00	84.00
1	FRONT BUMPER "KIA" LOGO	NECESSARY	72.00	32.00
1	FRONT BUMPER LOWER SKIRT	NOT NECESSARY	430.00	-
1	FRONT BUMPER LOWER BEAM	BENT / DISTORTED	85.00	85.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	348.00	-
1	RH HEADLAMP ASSY	BROKEN	1,050.00	1,050.00
1	RH FOG LAMP ASSY	NOT NECESSARY	288.00	-
1	RH FOG LAMP BRACKET	NOT NECESSARY	56.00	-
1	FRONT BONNET	DENTED / SCRAPED / DEFORMED	966.00	966.00
1	FRONT BONNET LOCK ASSY	TO REPAIR SEE LABOUR	85.50	-
1	RH FRONT FENDER	SCRAPED / BUCKLED / DISTORTED	420.00	420.00
1	RH FRONT FENDER SPLASH SHIELD	NOT NECESSARY	108.00	-
8	RH FRONT FENDER SPLASH SHIELD CLIP	NOT NECESSARY	48.00	-
1	WIPER WASHER RESERVOIR	NOT NECESSARY	170.00	-
1	FRONT SUPPORT PANEL ASSY	BROKEN	785.00	675.00
1	FRONT GRILLE SIGHT SHIELD	NOT NECESSARY	74.00	-
6	FRONT GRILLE CLIP	NECESSARY	24.00	24.00
1	FRONT GRILLE	LEG BENT / CRACKED	248.00	248.00
	LESS 20% DISCOUNT		-1,333.30	-922.60
			5,333.20	3,690.40

Report Ref No. CS1/LPM22009657/Eqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SIGNAL BULB SOCKET RH (SN)	BROKEN	20.00	20.00
1	SET HORN C/BRACKET (SN)	NOT NECESSARY	156.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	30.00	30.00
			206.00	50.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEAT AND STRAIGHTEN DAMAGED PARTS AND BODY PANELS. INCLUSIVE OF THE REPAIR OF FRONT BONNET LOCK ASSY.		1,500.00	1,000.00
	TO PUTTY AND SPRAY PAINT THE FRONT BUMPER, FRONT BONNET, FRONT FENDER, RH WHEELHOUSE PANEL AND NECESSARY AREAS.		1,250.00	600.00
	TO APPLY ANTI-RUST UNDERCOATING.		150.00	30.00
	TO REMOVE AND REFIT RADIATOR AND FAN UNIT TO FACILITATE THE REPAIRS.		150.00	50.00
	TO CHECK WIRING.		90.00	30.00
	TO REFOCUS HEADLAMP BEAMS TO SPECIFICATIONS.		90.00	30.00
	TO REMOVE AND REFIT AIRCON CONDENSER TO FACILITATE THE REPAIRS AND TO TOP UP GAS AFTER INSTALLATION.		150.00	120.00
	TO CHECK AND REALIGN WHEELS BY COMPUTERISED 4 -WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			3,500.00	1,860.00
GRAND TOTAL			9,039.20	5,600.40

RECOMMENDED COST OF REPAIRS			5,600.40
------------------------------------	--	--	-----------------

Report Ref No. CS1/LPM22009657/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.