

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22009660/EQY3Q2**Date:** 30/01/2023**REFERENCE**

Insured/Claimant: CHUA BEE HONG JANE (CAI MEIFENG JANE) Policy No: DMPG22007998  
Date of Loss: 16/09/2022 Nature of Claim: OD Claim No: CDMPG22001930

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMZ9986E**  
Make & Model: VOLVO S60, 1.6 D2 (A) Engine No: D4162T3269191  
Reg. Date: 27/06/2015 (Man. Year: 2015) Chassis No: YV1FS84ABF2365948  
Colour: Grey Odometer: 115461 km  
Engine Capacity: 1560 cc  
Market Value/New Car Price: S\$47,000.00  
Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm  
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,646.40	2,414.50	2,231.90	48.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,140.00	580.00	560.00	49.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,786.40</b>	<b>2,994.50</b>	<b>2,791.90</b>	<b>48.25</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,350.00</b>		
<b>- Excess (\$\$)</b>	0.00	500.00	-500.00	
<b>(\$\$)</b>	5,786.40	1,850.00	3,936.40	68.03
<b>+ GST 7.00/7.00% (\$\$)</b>	405.05	129.50	275.55	68.03
<b>Nett Amount (\$\$)</b>	<b>6,191.45</b>	<b>1,979.50</b>	<b>4,211.95</b>	<b>68.03</b>

**INSPECTION**

Date of Assignment: 30/09/2022 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)  
Date Inspected: 06/10/2022 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)  
Blk 3 Pioneer Road North, #01-18  
Singapore 628457  
Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2023)
Parts:	143	VOLVO S60 1.6 D2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ9986E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Crushed	2,016.00 F	*2,016.00 F
2	1		*FRT BUMPER RETAINER LH	Not Necessary	22.00 F	*- F
3	1		*REAR BUMPER UPPER SIDE BRACKET LH	Not Necessary	31.00 F	*- F
4	1		*RR BUMPER CTR BRACKET	Not Necessary	124.00 F	*- F
5	1		*RR BUMPER LOWER SPOILER	Cut	129.00 F	*129.00 F
6	1		*RR BUMPER REINFORCEMENT	Not Necessary	592.00 F	*- F
7	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 F
8	2		*REAR PARKING AID SENSOR	Not Necessary	260.00 F	*- F
9	1		*REAR EXHAUST PIPE	Not Necessary	1,000.00 F	*- F
						F=Franchise part.
					Sub Total (S\$)	4,224.00 2,195.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	422.40 219.50
					Total Parts (S\$)	4,646.40 2,414.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK, WELD,REMOVE & REPLACE ABOVE PARTS	New	400.00	250.00
2	TO PUTTY & RESRAY PAINTING ON AFFECTED AREAS	New	380.00	200.00
3	TO REMOVE & REFIT EXHAUST PIPE	New	150.00	0.00
4	TO CHECK WIRING	New	30.00	30.00
5	TO DIAGNOSE AND RESET FAULT CODE	New	180.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>1,140.00</b>	<b>580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >