

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22009661/TQY3Q2**Date:** 10/11/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR001393
Claimant Vehicle No :	SHA3426K	Insured Vehicle No :	SLB3026D
Date of Loss:	30/09/2022	Nature of Claim:	TP
		Claim No:	M2205406

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3426K		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU209657
Reg. Date:	03/05/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU145767
Colour:	Blue	Odometer:	569847 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,235.96	502.60	733.36	59.34
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	750.00	630.00	120.00	16.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,996.96	1,143.60	853.36	42.73
Approved Total (Overridden) (S\$)		900.00		
(S\$)	1,996.96	900.00	1,096.96	54.93
+ GST 7.00/7.00% (S\$)	139.79	63.00	76.79	54.93
Nett Amount (S\$)	2,136.75	963.00	1,173.75	54.93

INSPECTION

Date of Assignment:	30/09/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	03/10/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Nov 2022)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3426K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Repair	459.40 FL	*- FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	*- FL
5	1		*REAR BUMPER MAT	Not Necessary	50.00 F	*- F
6	1		*REAR BUMPER LOWER MOULDING	Deformed	155.00 FL	*155.00 FL
					Sub Total (\$\$)	1,532.45 628.25
					- List Item Discount on L Items 20.00/20.00% (\$\$)	296.49 125.65
					Total Parts (\$\$)	1,235.96 502.60

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
Gross Labour Cost (\$\$)			750.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >