

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009663/TWY3E2**Date:** 08/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00177932105

**Claimant Vehicle
No :** SLP8723T**Insured Vehicle
No :** SLH7000U

Date of Loss: 29/09/2022

Nature of Claim: TP

Claim
No: SNM22D206961/C02/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP8723T**

Make & Model: TOYOTA VIOS, 1.5 E CVT (A)

Engine No: 2NRX148917

Reg. Date: 21/06/2017 (Man. Year: 2017)

Chassis No: MHFB29F3002010352

Colour: Grey

Odometer: 413982 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16

Rear Tyre Size: 195/50 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,869.70	1,931.40	2,938.30	60.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,190.00	3,260.00	3,930.00	54.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,059.70	5,191.40	6,868.30	56.95
+ GST 7.00/7.00% (S\$)	844.18	363.40	480.78	56.95
Nett Amount (S\$)	12,903.88	5,554.80	7,349.08	56.95

INSPECTION

Date of Assignment: 07/11/2022

Date Inspected: 30/09/2022

Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2022)
Parts:	143	TOYOTA VIOS 1.5 E CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP8723T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*REAR REGN PLATE	Bent	80.00 FS	*80.00 FS
3	1		*COVER ,RR BUMPER ,L/	Deformed	565.60 FS	*565.60 FS
4	1		*REINFORCEMENT SUB-AS	Not Necessary	360.10 FS	*- FS
5	1		*SUPPORT ,RR BUMPER S	Deformed	25.00 FS	*25.00 FS
6	1		*SUPPORT ,RR BUMPER S	Not Necessary	25.00 FS	*- FS
7	1		*SEAL ,RR BUMPER SIDE	Not Necessary	65.00 FS	*- FS
8	1		*SEAL ,RR BUMPER SIDE	Not Necessary	65.00 FS	*- FS
9	10		*PIECE RR BUMPER	Necessary	48.00 FS	*45.00 FS
10	1		*PANEL SUB-ASSY ,BODY	Not Necessary	775.70 FS	*- FS
11	1		*PANEL SUB-ASSY ,LUGG	Bent	852.90 FS	*852.90 FS
12	1		*WEATHERSTRIP ,LUGGAG	Not Necessary	190.10 FS	*- FS
13	1		*ARM SUB-ASSY ,LUG CO	Not Necessary	65.00 FS	*- FS
14	1		*ARM SUB-ASSY ,LUG CO	Not Necessary	65.00 FS	*- FS
15	1		*LOCK ASSY ,LUGGAGE C	Not Necessary	101.80 FS	*- FS
16	1		*PLATE ,LUGGAGE COMPT	Necessary	49.40 FS	*49.40 FS
17	1		*EMBLEM ,SYMBOL	Necessary	57.50 FS	*57.50 FS
18	1		*PLATE ,LUGGAGE COMPT	Necessary	38.50 FS	*38.50 FS
19	1		*LAMP ASSY ,RR COMBIN	Not Necessary	345.90 FS	*- FS
20	1		*LAMP ASSY ,RR COMBIN	Not Necessary	345.90 FS	*- FS
21	1		*LAMP ASSY ,LICENSE	Not Necessary	70.80 FS	*- FS
22	1		*LAMP ASSY ,RR RH	Not Necessary	205.00 FS	*- FS
23	1		*LAMP ASSY ,RR LH	Not Necessary	205.00 FS	*- FS
24	1		*BACK SENSOR GREY METALLIC	Not Working	167.50 FS	*167.50 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,869.70	1,931.40
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING & CONDUCT LEAK TEST	New	180.00	180.00
2	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
3	DRILL HOLE & INSTALL REVERSE SENSOR	New	180.00	180.00
4	SUPPLY SEALANT	New	100.00	100.00
5	R/I REAR BOOT INTERIOR TRIMMING	New	720.00	0.00
6	REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA	New	2,880.00	1,440.00
7	RESPRAY ACC AFF AREA	New	2,950.00	1,180.00
Gross Labour Cost (\$\$)			7,190.00	3,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >