



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 103G

| Qty                | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|---|----------------------|---------------------------|-------------------|
|                    | <b><u>REPLACEMENT OF PARTS</u></b>  |                      |                           |                   |
| 1                  | LINER, FR FENDER, LH  | NOT NECESSARY        | 219.10                    | -                 |
| 1                  | HINGE ASSY, FRONT DOOR, UPPER LH  | NOT NECESSARY        | 105.50                    | -                 |
| 1                  | HINGE ASSY, FRONT DOOR, LOWER LH  | NOT NECESSARY        | 120.00                    | -                 |
| 1                  | DOOR ASSY FRONT LH  | TO REPAIR SEE LABOUR | 2,536.93                  | -                 |
| 1                  | FENDER SUB-ASSY, FR, LH   | TO REPAIR SEE LABOUR | 1,060.70                  | -                 |
|                    |   |                      | 4,042.23                  | -                 |
|                    | <b><u>LABOUR</u></b>  |                      |                           |                   |
|                    | PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF DOOR ASSY FRONT LH AND FENDER SUB-ASSY, FR, LH. |                      | 676.00                    | 300.00            |
|                    | SPRAY PAINT.  |                      | 756.00                    | 400.00            |
|                    | TO WASH AND VACUUM.   | NOT NECESSARY        | 60.00                     | -                 |
|                    | TO CHECK WIRING AND SYSTEM FUNCTION.  | NOT NECESSARY        | 120.00                    | -                 |
|                    | TO APPLY RUST-PROOFING ON AFFECTED AREA.  | NOT NECESSARY        | 100.00                    | -                 |
|                    | TO REPLACE SUNDRY PARTS.  | NOT NECESSARY        | 100.00                    | -                 |
|                    |   |                      | 1,812.00                  | 700.00            |
| <b>GRAND TOTAL</b> |   |                      | <b>5,854.23</b>           | <b>700.00</b>     |

|   |  |  |               |
|---|--|--|---------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b> |  |  | <b>200.00</b> |
|---|--|--|---------------|

Report Ref No. NS/INC22009675/Rwce2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.