



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGB 404A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR RH (CONSISTENT)	BENT	1,753.86	1,753.86
1	FRONT DOOR RUBBER STRIPE RH (CONSISTENT)	NECESSARY	300.63	300.63
1	FRONT DOOR LOWER HINGE RH (CONSISTENT)	NOT NECESSARY	135.75	-
1	SET SIDE SKIRT RH CLIP (CONSISTENT)	NOT NECESSARY	50.00	-
1	FRONT FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	753.34	-
	LESS 10% DISCOUNT		-299.36	-205.45
			2,694.22	1,849.04
<u>SPECIAL NETT ITEMS</u>				
1	RIM (SN) (CONSISTENT)	SCRATCHED	850.00	400.00
			850.00	400.00
<u>LABOUR</u>				
	TO STRAIGHTEN AND PANEL BEATING REAR MEMBER .TO REMOVE AND REPLACE THE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		700.00	500.00
	TO PUTTY ,RE-SPRAY PAINTING AND POLISH AFFECTED AREAS .		800.00	600.00
	TO TRANSFER DOOR COMPONENTS.		120.00	60.00
	TO CONDUCT ELECTRONIC ALIGNMENT.		150.00	60.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	40.00
	TO RUST PROOF AFFECTED AREAS .		50.00	30.00
			1,900.00	1,290.00
GRAND TOTAL			5,444.22	3,539.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CC4/ASM22009681/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.