

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22009683/AWY3Q2**Date:** 23/12/2022**REFERENCE**

Insured/Claimant:	AXEL BADER	Policy No:	SP2001207703	
Date of Loss:	29/09/2022	Nature of Claim:	OD	Claim No: 202222007155JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ7843G		
Make & Model:	AUDI A3, 1.5 SEDAN TFSI S TRONIC (18") (A)	Engine No:	CHZC27715
Reg. Date:	20/03/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V0KA059576
Colour:	Grey	Odometer:	13710 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$102,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,075.00	1,661.80	11,413.20	87.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,852.00	1,952.00	900.00	31.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,927.00	3,613.80	12,313.20	77.31
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	15,327.00	3,013.80	12,313.20	80.34
+ GST 7.00/7.00% (\$\$)	1,072.89	210.97	861.92	80.34
Nett Amount (\$\$)	16,399.89	3,224.77	13,175.12	80.34

INSPECTION

Date of Assignment:	03/10/2022	
Date Inspected:	05/10/2022	Inspected At: Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2 Singapore 159938
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts:	143	AUDI A3 1.5 SEDAN TFSI S TRONIC (18") (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ7843G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,146.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	43.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	179.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	332.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT -RH	Not Necessary	318.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,578.00 FS	*1,578.00 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	210.00 FS	*- FS
9	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*8.30 FS
10	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*15.50 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	210.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	211.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	136.00 FS	*- FS
15	1		*HEADLIGHT -RH	Not Necessary	5,879.00 FS	*- FS
16	1		*LIFT CYLINDER -RH	Not Necessary	156.00 FS	*- FS
17	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
18	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
19	1		*RADIATOR AIR GUIDE-RH	Not Necessary	28.00 FS	*- FS
20	1		*RADIATOR AIR GUIDE OUTER SEAL -RH	Not Necessary	9.00 FS	*- FS
21	1		*RADIATOR AIR GUIDE -UPPER CENTRE	Not Necessary	14.00 FS	*- FS
22	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
23	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 13,075.00 1,661.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	700.00
4	TO RESPRAY FRONT BUMPER	New	900.00	700.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,852.00	1,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >