

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009684/KQY3Q2**Date:** 17/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00090052200		
Claimant Vehicle No :	SGV7181R	Insured Vehicle No :	SMW9040A		
Date of Loss:	28/09/2022	Nature of Claim:	TP	Claim No:	SNM22D206954/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV7181R	Engine No:	K20Z22500893
Make & Model:	HONDA CIVIC, 2.0 (A)	Chassis No:	JHMF26407S200893
Reg. Date:	25/06/2007 (Man. Year: 2007)	Odometer:	409302 km
Colour:	Metallic Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,431.44	4,793.72	8,637.72	64.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,330.00	1,800.00	3,530.00	66.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,761.44	6,593.72	12,167.72	64.85
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	18,761.44	5,200.00	13,561.44	72.28
+ GST 8.00/8.00% (S\$)	1,500.92	416.00	1,084.92	72.28
Nett Amount (S\$)	20,262.36	5,616.00	14,646.36	72.28

INSPECTION

Date of Assignment:	30/09/2022	
Date Inspected:	30/09/2022	Inspected At: H C Auto Pte Ltd (HQ) 160 Sin Ming Drive, #05-09 Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	143	HONDA CIVIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV7181R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,090.70 FL	*687.00 FL
2	1		*BOOT LID INNER LOCK	Dented	257.30 FL	*194.90 FL
3	1		*BOOT LID LOCK CATCH	Repair	27.00 FL	*- FL
4	2		*BOOT LID HINGE	Repair	510.00 FL	*- FL
5	2		*BOOT LID HINGE GARNISH	Serviceable	400.00 FL	*- FL
6	1		*BOOT LID HONDA LOGO	Necessary	101.30 FL	*101.30 FL
7	2		*BOOT LID REFLECTOR	Serviceable	369.60 FL	*- FL
8	2		*BOOT LID NO PLATE LAMP	Serviceable	57.60 FL	*- FL
9	1		*BOOT LID NO PLATE LAMP GARNISH	Serviceable	101.30 FL	*- FL
10	1		*BOOT LID INNER TRIM	Serviceable	321.00 FL	*- FL
11	1		*BOOT LID WEATHERSTRIP (50%)	Distorted / Dented	70.08 FS	*43.80 FS
12	1		*REAR BUMPER FASCIA	Bent	801.20 FL	*683.40 FL
13	2		*REAR BUMPER SIDE RETAINER	Distorted	46.40 FL	*46.40 FL
14	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
15	1		*REAR BUMPER LOWER LIP	Bent	850.00 FL	*850.00 FL
16	2		*REAR FENDER INNER GARNISH	Serviceable	628.00 FL	*- FL
17	1		*REAR END PANEL	Bent	289.50 FL	*289.50 FL
18	1		*REAR END PANEL INNER SHIELD	Serviceable	145.00 FL	*- FL
19	2		*TAIL LAMPS	Cracked	591.40 FL	*591.40 FL
20	2		*TAIL LAMP PANEL	Repair	318.80 FL	*- FL
21	1		*REAR FLOOR PANEL	Repair	911.40 FL	*- FL
22	1		*REAR EXHAUST BOX	Bent	3,500.00 FL	*810.10 FL
23	1		*REAR EXHAUST ALUMINIUM COVER	Repair	191.00 FL	*- FL
24	1		*REAR EXHAUST BOX CENTER	Bent	1,800.00 FL	*1,052.60 FL
25	6		*REAR EXHAUST MOUNTING	Serviceable	350.10 FL	*- FL
26	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	83.00 FL	*- FL
27	1		*REAR SPARE TYRE BOARD	Dented	308.30 FL	*308.30 FL
28	1		*REAR SPARE TYRE HOLDER	Serviceable	19.80 FL	*- FL
29	1		*REAR END PANEL INNER GARNISH (CARBON)	Serviceable	350.00 FS	*- FS
30	1		*REAR CAMERA	Serviceable	450.00 FS	*- FS
31	1		*REAR PANEL SEAL	Necessary	250.00 FS	*30.00 FS
32	4		*REAR REVERSE SENSOR	Dented	907.60 FS	*200.00 FS
33	1		*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
34	1		*REAR WINDSCREEN GLASS INNER GUM	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,252.38	5,923.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,820.94	1,129.98
Total Parts (\$\$)	13,431.44	4,793.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	2,200.00	700.00
2	TO PUTTY AND SPRAY PAINTING	New	2,000.00	800.00
3	TO RE-SEAL ANTI RUST	New	200.00	60.00
4	TO CHECK WIRING & RESET FAULT CODE	New	120.00	20.00
5	REMOVE REAR EXHAUST BOX	New	180.00	80.00
6	REMOVE AND REFIX REAR REVERSE SENSOR	New	120.00	60.00
7	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	160.00	0.00
8	REMOVE AND REFIX REAR CUSHION SEAT ,GARNISH ,CARPET ETC	New	350.00	80.00
Gross Labour Cost (S\$)			5,330.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >