



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 8717T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	NOT NECESSARY	559.80	-
1	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	25.80	-
1	FRONT FENDER - RH	DENTED	328.60	328.60
1	FRONT FENDER TOP QUARTER GARNISH	NOT NECESSARY	65.00	-
1	FRONT FENDER INNER SHIELD	TWISTED	57.50	57.50
1	FRONT DOOR - RH	TO REPAIR SEE LABOUR	1,258.00	-
1	FRONT DOOR RUBBER	NOT NECESSARY	145.00	-
2	FRONT DOOR HINGES	NOT NECESSARY	110.00	-
1	FRONT WHEEL HUB	NOT NECESSARY	175.70	-
1	FRONT WHEEL BEARING	NOT NECESSARY	114.20	-
1	FRONT SHOCK ABSORBER	NOT NECESSARY	433.20	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	286.30	-
1	FRONT LOWER ARM	NOT NECESSARY	264.30	-
	LESS 20% DISCOUNT		-764.68	-77.22
			3,058.72	308.88
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	60.00	-
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	50.00	50.00
1	ROCKER PANEL GARNISH O/S (SN)	TORN	400.00	400.00
1	FRONT WHEEL RIM - RH (SN)	WARPED	850.00	400.00
			1,360.00	850.00
<u>LABOUR</u>				
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	NOT NECESSARY	400.00	-
	TO CONDUCT WHEEL ALIGNMENT.		180.00	60.00
	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.	NOT NECESSARY	180.00	-
	TO APPLY UNDERCOATING.		150.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT DOOR - RH.		1,400.00	300.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,200.00	750.00
			3,590.00	1,140.00
GRAND TOTAL			8,008.72	2,298.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CS/SMR22009686/Uny3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.