

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22009688/UCY3E2**Date:** 24/11/2022**REFERENCE****Insured/Claimant:** HI&M **Policy No:** DMB1SNW00001272200**Date of Loss:** 14/09/2022 **Nature of Claim:** OD **Claim No:** SNM22D206968/C01/TAYHP**DESCRIPTION & IDENTIFICATION OF VEHICLE**

**Reg No:** PC5624L  
**Make & Model:** TOYOTA HIACE, 3.0 D Commuter (M) **Engine No:** 1KD2595936  
**Reg. Date:** 13/01/2017 (Man. Year: 2016) **Chassis No:** KDH2230027326  
**Colour:** White/Blue **Odometer:** 0 km  
**Engine Capacity:** 2982 cc  
**Market Value/New Car Price:** S\$60,000.00  
**Sum Insured (S\$):** **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

**General Condition:** **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

**CONDITION OF TYRES**

**Front Tyre Size:** 195 R15 **Rear Tyre Size:** 195 R15  
**Front Left Side:** Achilles 7 mm **Rear Left Side:** Achilles 7 mm  
**Front Right Side:** Achilles 7 mm **Rear Right Side:** Achilles 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (S\$)</b>	0.00	2,000.00	-2,000.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>-2,000.00</b>	<b>2,000.00</b>	

**INSPECTION**

**Date of Assignment:** 03/10/2022 **Present Location:** Car City Auto Centre Pte Ltd (HQ)  
Car City Auto Centre Pte Ltd (HQ)  
**Date Inspected:** 04/10/2022 **Inspected At:** Blk 9006 #01-198, Tampines Street 93  
Singapore 528840  
**Estimated Period of Repair:** 0.0 days

**Adjuster:** MARCUS CHUA**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$60,000.00
OMV :	\$42,335.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$45,660.00
COE Rebate (2) :	\$19,970.00
Total Rebate (1) + (2) = :	\$19,970.00

The total amount incurred will be Market Value \$60,000.00 minus Total Rebate \$19,970.00 = \$40,030.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Nov 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D Commuter (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5624L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >