10/21/22, 11:10 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS3/CTI22009690/SVY3E2 Our File No:

21/10/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00184692202

Claimant Vehicle

SMQ5030L

Insured Vehicle No:

SMD4909C

No:

Nature of

Claim

Odometer:

Date of Loss:

23/09/2022

TP Claim:

SNM22D206855/C02/KHONGLH

120730 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMQ5030L Reg No:

MERCEDES-BENZ A180, 1.6 (A) Make & Model: Engine No: 27091031261403 Reg. Date: 19/06/2017 (Man. Year: 2017) Chassis No: WDD1760422J594726

Colour: Yellow

Engine Capacity: 1595 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date Inspected:

Date of Assignment: 03/10/2022

Nxpress Performance Pte Ltd (HQ)

25, Kaki Bukit Road 4, Synergy @ KB, #01-39,

Singapore 417800

Contact: Mr Pan(Ah Nam) 82170834

Estimated Period of Repair: 12.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal Manager: **VERON CHEN**

03/10/2022 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$18,000.00 -\$20,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 Oct 2022)

Parts: N/A MERCEDES-BENZ A180 1.6 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMQ5030L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

10/21/22, 11:10 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >