3/19/23, 11:43 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III22009692/UPA3Q2

**Date:** 19/03/2023

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826\_02

Claimant Vehicle SJK8361D Insured Vehicle No: SMX2301M

Date of Loss: 28/09/2022 Nature of Claim: TP Claim No: MFL2022D0005683

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJK8361D

 Make & Model:
 TOYOTA ALLION, 1.5 (A)
 Engine No:
 1NZD177921

 Reg. Date:
 05/11/2008 (Man. Year: 2008)
 Chassis No:
 NZT2603032149

 Colour:
 Blue
 Odometer:
 256718 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
Front Left Side: APLUS 7 mm Rear Left Side: APLUS 7 mm
Front Right Side: APLUS 7 mm Rear Right Side: APLUS 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,080.20	2,410.37	6,669.83	73.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,380.00	1,870.00	57.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,330.20	3,790.37	8,539.83	69.26
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	12,330.20	3,000.00	9,330.20	75.67
+ Car Rental (4.0 x S\$	100.00/day) (S\$)	400.00		
+ Doc/	Search Fee (S\$)	7.45		
N	ett Liability (S\$)	3,407.45		
Global Sum	Settlement (S\$)	3,400.00		

**INSPECTION** 

Date of Assignment: 03/10/2022

Choo Motor Spray Painter (HQ)

Date Inspected: 03/10/2022 Inspected At: 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki

Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Oct 2022)

Parts: 143 TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK8361D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,266.10 F	*- FL
2	1		*BOOTLID REAR LOGO	Not Necessary	68.50 F	*- FL
3	1		*BOOTLID INNER LOCK	Not Necessary	409.10 F	*- FL
4	1		*BOOTLID LOCK STRICKER	Not Necessary	66.80 F	*- FL
5	1		*BOOTLID WEATHERSTRIP	Not Necessary	282.30 F	*- FL
6	1		*BOOTLID ANTENNA SENSOR	Not Necessary	366.10 F	*- FL
7	1		*REAR BUMPER	Dented / Cracked	1,655.10 F	*1,450.00 FL
8	1		*REAR BUMPER BRACKETS	O/S Bent	210.00 F	*105.00 FL
9	1		*REAR BUMPER REFLECTORS	O/S Cracked	120.00 F	*60.00 FL
10	1		*REAR BUMPER SIDE RETAINERS	O/S Bent	130.00 F	*65.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
12	1		*REAR END PANEL	Dented	788.20 F	*788.20 FL
13	1		*REAR END PANEL TOP GARNISH	Twisted	362.30 F	*362.30 FL
14	2		*TAILLAMPS	Not Necessary	1,160.00 F	*- FL
15	1		*REAR FLOOR PANEL	Not Necessary	1,145.20 F	*- FL
16	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	420.50 F	*- FL
17	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
18	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
19	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	9,080.20	3,130.50
	- List Item Discount on L Items 0.00/25.00% (S\$)				0.00	720.13
				Total Parts (S\$)	9,080.20	2,410.37

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	30.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,000.00	600.00
7	TO PUTTY & SPRAY PAINTING	New	1,800.00	600.00
		Gross Labour Cost (S\$)	3,250.00	1,380.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >