

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009696/AVY3Q2**Date:** 22/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00035992200
Claimant Vehicle No :	SNF2980K	Insured Vehicle No :	SJB45S
Date of Loss:	29/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D207010/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF2980K	Engine No:	4B11CH1131
Make & Model:	MITSUBISHI LANCER, 2.0 (A)	Chassis No:	JMYSTCY4A9U001145
Reg. Date:	15/12/2008 (Man. Year: 2008)	Odometer:	182677 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,278.75	5,881.91	4,396.84	42.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	2,180.00	1,270.00	36.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,728.75	8,061.91	5,666.84	41.28
Approved Total (Overridden) (S\$)		6,400.00		
(S\$)	13,728.75	6,400.00	7,328.75	53.38
+ GST 7.00/7.00% (S\$)	961.01	448.00	513.01	53.38
Nett Amount (S\$)	14,689.76	6,848.00	7,841.76	53.38

INSPECTION

Date of Assignment:	03/10/2022	
Date Inspected:	04/10/2022 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2022)
Parts:	143	MITSUBISHI LANCER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF2980K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	693.00 FL	*693.00 FL
2	1		*REAR BOOTLID GT EMBLEM	Necessary	40.00 FL	*40.00 FL
3	1		*REAR BOOTLID LOGO EMBLEM	Necessary	41.80 FL	*41.80 FL
4	1		*REAR BOOTLID INNER TRIM GARNISH	Torn	267.00 FL	*267.00 FL
5	1		*REAR BOOTLID LOCK	Damaged	161.00 FL	*161.00 FL
6	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	30.00 FL	*- FL
7	2		*REAR BOOTLID REFLECTOR BACK GASKET SEAL L/R	Not Necessary	40.00 FL	*- FL
8	1		*REAR BOOTLID REFLECTOR L/R	N/S Cracked	350.00 FL	*175.00 FL
9	1		*REAR BOOTLID WEATHERSTRIP	Cut	155.00 FL	*155.00 FL
10	1		*REAR BUMPER BEAM	Bent	138.50 FL	*138.50 FL
11	2		*REAR BUMPER END SEAL COVER L/R	Not Necessary	96.00 FL	*- FL
12	1		*REAR BUMPER REFLECTOR L/R	N/S Missing	67.20 FL	*33.60 FL
13	1		*REAR BUMPER REINFORCEMENT	Dented	210.00 FL	*210.00 FL
14	2		*REAR BUMPER SIDE RETAINER L/R	Damaged	100.00 FL	*100.00 FL
15	1		*REAR BUMPER TOW HOOK COVER	Damaged	22.00 FL	*22.00 FL
16	1		*REAR END PANEL	Dented	506.00 FL	*506.00 FL
17	1		*REAR END PANEL ANTENNA SENSOR	Cracked	165.00 FL	*165.00 FL
18	1		*REAR END PANEL BUZZLE SENSOR	Cracked	119.70 FL	*119.70 FL
19	1		*REAR END PANEL INNER TOP GARNISH	Deformed	191.00 FL	*191.00 FL
20	1		*REAR EXHAUST SILENCER GASKET	Not Necessary	23.00 FL	*- FL
21	1		*REAR EXHAUST SILENCER HEAT SHIELD COVER	Crumpled	195.00 FL	*195.00 FL
22	2		*REAR EXHAUST SILENCER RUBBER MOUNTING	Not Necessary	110.00 FL	*- FL
23	2		*REAR FENDER INNER TRIM GARNISH L/R	Torn	533.40 FL	*533.40 FL
24	2		*REAR NUMBER PLATE LAMP L/R	Missing	130.00 FL	*130.00 FL
25	1		*REAR SPARE TYRE BOARD	Torn	222.90 FL	*222.90 FL
26	2		*REAR TAILLAMP L/R	Cracked	640.00 FL	*640.00 FL
27	2		*REAR TAILLAMP PANEL L/R	Dented	190.00 FL	*190.00 FL
28	1		*SET REAR BOOTLID INNER TRIM GARNISH CLIPS	Necessary	40.00 FS	*30.00 FS
29	1		*REAR BUMPER ASSY	Distorted	2,200.00 FS	*1,000.00 FS
30	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
32	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
34	1		*REAR EXHAUST SILENCER BOX ASSY	Repair	2,300.00 FS	*- FS
35	2		*SET REAR FENDER INNER TRIM GARNISH CLIPS L/R	Necessary	100.00 FS	*60.00 FS
36	1		*REAR NUMBER PLATE	Missing	25.00 FS	*25.00 FS
37	1		*REAR SPARE TYRE PANEL INSULATOR PAD	Not Necessary	250.00 FS	*- FS
38	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,822.50	6,374.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	543.75	492.99
Total Parts (\$\$)	10,278.75	5,881.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	120.00	60.00
3	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL ,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER	New	1,600.00	1,000.00
4	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDNET	New	150.00	80.00
5	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,400.00	900.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
Gross Labour Cost (\$\$)			3,450.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >