

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG122009697/KVY3Q2**Date:** 10/05/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SNB3798K **Insured Vehicle No :** GBE36Y

Date of Loss: 24/08/2022 Nature of Claim: TP Claim No: CDMCG22002860

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNB3798K**

Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 1NZ9312654

Reg. Date: 19/08/2021 (Man. Year: 2021) Chassis No: JTDZZ9H370L000799

Colour: Metallic Blue Odometer: 112635 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Wanli 4 mm Rear Left Side: Wanli 5 mm

Front Right Side: Wanli 4 mm Rear Right Side: Wanli 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,264.07	1,282.72	1,981.35	60.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,510.00	770.00	6,740.00	89.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,774.07</b>	<b>2,052.72</b>	<b>8,721.35</b>	<b>80.95</b>
<b>+ GST 8.00/8.00% (S\$)</b>	861.93	164.22	697.71	80.95
<b>Nett Amount (S\$)</b>	<b>11,636.00</b>	<b>2,216.94</b>	<b>9,419.06</b>	<b>80.95</b>

**INSPECTION**

Date of Assignment: 03/10/2022

Date Inspected: 04/10/2022 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB3798K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FR BUMPER	Mtg Cracked	366.80 FL	*366.80 FL
2	1		*MIRROR ASSY ,OUTER ,RH	Repair	1,219.60 FL	*- FL
3	1		*COVER ,OUTER MIRROR ,RH	Repair	127.90 FL	*- FL
4	1		*COVER ,FOG LAMP ,RH	Scratched	116.90 FL	*116.90 FL
5	1		*PANEL ,FR FENDER RH	Repair	584.60 FL	*- FL
6	1		*LINER ,FR FENDER ,RH	Serviceable	174.40 FL	*- FL
7	1		*EMBLEM ,SIDE PANEL	Necessary	46.00 FL	*46.00 FL
8	1		*RIM	Serviceable	395.30 FL	*- FL
9	1		*FR RH HEADLAMP	Cut	1,100.60 FL	*1,100.60 FL
10	1		*SET FRONT BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
11	1		*FENDER LINER CLIP	Not Necessary	70.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					4,297.10	1,690.30
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,033.03	407.58
Total Parts (\$\$)					3,264.07	1,282.72

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	300.00
3	TO REMOVE AND REFIT ELECTRICAL WIRING BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODY REPAIR	New	480.00	0.00
4	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
5	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
8	TOWING FEES	New	150.00	0.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	450.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
11	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
12	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,510.00</b>	<b>770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >