

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22009702/GQY3Q2**Date:** 20/03/2023**REFERENCE**

Insured/Claimant:	HO SENG TAI	Policy No:	SP2002495301-01	
Date of Loss:	30/09/2022	Nature of Claim:	OD	Claim No: 202222007179

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG1485Z		
Make & Model:	MERCEDES-BENZ E200, 2.0 EXCLUSIVE (R18 LED) (A)	Engine No:	27492030707523
Reg. Date:	21/09/2016 (Man. Year: 2016)	Chassis No:	WDD2130422A042689
Colour:	Brown	Odometer:	65277 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,130.85	10,557.25	6,573.60	38.37
Miscellaneous Items	40.00	40.00	0.00	0.00
Labour	1,030.00	830.00	200.00	19.42
Paintwork Labour	980.00	900.00	80.00	8.16
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,180.85	12,327.25	6,853.60	35.73
+ GST 7.00/8.00% (S\$)	1,342.66	986.18	356.48	26.55
Nett Amount (S\$)	20,523.51	13,313.43	7,210.08	35.13

INSPECTION

Date of Assignment:	03/10/2022	Present Location:	Kan Fook Sing Motor Workshop (Defu) Kan Fook Sing Motor Workshop (Defu) Blk 8 Defu South Street 1, Defu Industrial City #04-29 Singapore 533758
Date Inspected:	04/10/2022	Inspected At:	
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
Parts:	143	MERCEDES-BENZ E200 2.0 EXCLUSIVE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG1485Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Buckled	1,350.00 F	*1,120.00 F
2	1		*FRONT BONNET STAR (WCP)	Bent	55.00 F	*55.00 F
3	1		*FRONT BONNET SPRING STOPPER RH (WCP)	Not Necessary	22.00 F	*- F
4	1		*FRONT BONNET SPRING STOPPER LH (WCP)	Not Necessary	22.00 F	*- F
5	1		*FRONT BONNET HOOK RH (WCP)	Not Necessary	46.00 F	*- F
6	1		*FRONT BONNET HOOK LH (WCP)	Not Necessary	46.00 F	*- F
7	1		*FRONT BONNET LOCK TOP (WCP)	Not Necessary	46.00 F	*- F
8	1		*FRONT BONNET LOCK LOWER RH (WCP)	Not Necessary	48.00 F	*- F
9	1		*FRONT BONNET LOCK LOWER LH (WCP)	Not Necessary	48.00 F	*- F
10	1		*FRONT BONNET HINGE RH (WCP)	Not Necessary	135.00 F	*- F
11	1		*FRONT BONNET HINGE LH (WCP)	Not Necessary	135.00 F	*- F
12	1		*FRONT SUPPORT PANEL (WCP)	Distorted	1,300.00 F	*470.00 F
13	1		*FRONT SUPPORT TOP AIR DUCT (WCP)	Not Necessary	555.00 F	*- F
14	1		*FRONT BRACE PANEL (WCP)	Not Necessary	80.00 F	*- F
15	1		*FRONT GRILLE (WCP)	Cracked	545.00 F	*545.00 F
16	1		*FRONT GRILLE TOP BEAM (WCP)	Bent	150.00 F	*125.00 F
17	1		*FRONT BUMPER TOP RUBBER (WCP)	Not Necessary	20.00 F	*- F
18	1		*FRONT GRILLE CAMERA (WCP)	Not Necessary	860.00 F	*- F
19	1		*FRONT HEADLAMP RH (WCP)	Cracked	1,800.00 F	*1,650.00 F
20	1		*FRONT HEADLAMP LH (WCP)	Broken	1,800.00 F	*1,714.00 F
21	1		*FRONT FENDER RH (WCP)	Not Necessary	650.00 F	*- F
22	10		*FRONT FENDER SHIELD CLIP (WCP)	Not Necessary	60.00 F	*- F
23	1		*FRONT BUMPER (WCP)	Deformed	850.00 F	*850.00 F
24	1		*FRONT BUMPER CARRIER CENTRE (WCP)	Not Necessary	80.00 F	*- F
25	1		*FRONT BUMPER CARRIER RH (WCP)	Broken	50.00 F	*56.00 F
26	1		*FRONT BUMPER CARRIER LH (WCP)	Not Necessary	50.00 F	*- F
27	1		*FRONT BUMPER FOAM (WCP)	Broken	110.00 F	*98.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	315.00 F	*280.00 F
29	1		*FRONT BUMPER REINFORCEMENT BRACKET RH (WCP)	Not Necessary	145.00 F	*- F
30	1		*FRONT BUMPER REINFORCEMENT BRACKET LH (WCP)	Not Necessary	145.00 F	*- F
31	1		*FRONT BUMPER LOWER GRILLE (WCP)	Not Necessary	65.00 F	*- F
32	1		*FRONT BUMPER FOGLAMP COVER RH (WCP)	Not Necessary	60.00 F	*- F
33	1		*FRONT BUMPER FOGLAMP COVER LH (WCP)	Not Necessary	60.00 F	*- F
34	1		*FRONT BUMPER FOGLAMP CHROME RH (WCP)	Not Necessary	50.00 F	*- F
35	1		*FRONT BUMPER FOGLAMP CHROME LH (WCP)	Not Necessary	50.00 F	*- F
36	1		*FRONT BUMPER LOWR GARNISH (WCP)	Cracked	85.00 F	*80.00 F
37	1		*FRONT BUMPER LOWER GARNISH CHROME (WCP)	Broken	85.00 F	*80.00 F
38	1		*AIR BUFFLER TOP (WCP)	Bent	80.00 F	*82.00 F
39	1		*AIR BUFFLER LOWER (WCP)	Not Necessary	95.00 F	*- F
40	1		*AIR CON CONDENSER (WCP)	Bent	885.00 F	*860.00 F
41	1		*RADIATOR (WCP)	Bent	600.00 F	*600.00 F
42	1		*RADIATOR FAN ASSY (WCP)	Not Necessary	1,000.00 F	*- F
43	1		*FRONT NUMBER PLATE GARNISH (WCP)	Cracked	68.00 F	*60.00 F
44	10		*FRONT BUMPER CLIP (WCP)	Necessary	60.00 F	*60.00 F
<u>Supplementary #1</u>						
45	1		*RADAR SENSOR BRACKET (WCP)	Broken	10.00 F	*10.00 F
46	1		*AIR BUFFLE (LH) (WCP)	Broken	36.00 F	*36.00 F
47	1		*AIR BUFFLE (RH) (WCP)	Broken	37.00 F	*37.00 F
48	1		*RADIATOR COOLANT HOSE (WCP)	Bent	80.00 F	*80.00 F
49	1		*SUPPORT PANEL BRACE SUPPORT RH (WCP)	Bent	35.00 F	*35.00 F
50	1		*SUPPORT PANEL BRACE SUPPORT LH (WCP)	Bent	35.00 F	*35.00 F
51	1		*RADIATOR NO. 2 (WCP)	Bent	570.00 F	*570.00 F
52	1		*FASTENTING PLATE STRUT (WCP)	Necessary	9.50 F	*9.50 F

F=Franchise part.

Sub Total (\$\$)	15,573.50	9,597.50
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,557.35	959.75
Total Parts (\$\$)	17,130.85	10,557.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE (BENT)	40.00	40.00
Sub Total (\$\$)			40.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	980.00	900.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	100.00	100.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	880.00	700.00
Gross Labour Cost (\$\$)			2,010.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >