



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

65277

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002495301-01	Date of Loss:	30/09/2022
Vehicle Reg. No.:	SLG1485Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HO SENG TAI		
Make/Model:	MERCEDES-BENZ E200, 2.0 EXCLUSIVE (R18 LED) (A)	Vehicle Reg. Date:	22/09/2016
Vehicle Colour:	METALLIC BROWN	Chassis No:	WDD2130422A042689
Engine No:	2742030707523		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	16,237.10
Miscellaneous Items	40.00
Labour	1,030.00
Paintwork Labour	980.00
Towing	0.00
Gross Total (\$\$)	18,287.10
+ GST 7.00% (\$\$)	1,280.10
Nett Amount (\$\$)	19,567.20

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Oct 2022)

Parts: 143 MERCEDES-BENZ E200 2.0 EXCLUSIVE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SLG1485Z/03/10/2022 12:40

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET / Bu	0.00	0.00	*1,350.00 F
2	1		*FRONT BONNET STAR / BT	0.00	0.00	*55.00 F
3	1		*FRONT BONNET SPRING STOPPER RH ?	0.00	0.00	*22.00 F
4	1		*FRONT BONNET SPRING STOPPER LH ?	0.00	0.00	*22.00 F
5	1		*FRONT BONNET HOOK RH X	0.00	0.00	*46.00 F
6	1		*FRONT BONNET HOOK LH X	0.00	0.00	*46.00 F
7	1		*FRONT BONNET LOCK TOP X	0.00	0.00	*46.00 F
8	1		*FRONT BONNET LOCK LOWER RH ?	0.00	0.00	*48.00 F
9	1		*FRONT BONNET LOCK LOWER LH ?	0.00	0.00	*48.00 F
10	1		*FRONT BONNET HINGE RH ?	0.00	0.00	*135.00 F
11	1		*FRONT BONNET HINGE LH ?	0.00	0.00	*135.00 F
12	1		*FRONT SUPPORT PANEL / H/S	0.00	0.00	*1,300.00 F
13	1		*FRONT SUPPORT TOP AIR DUCT / de	0.00	0.00	*555.00 F
14	1		*FRONT BRACE PANEL ?	0.00	0.00	*80.00 F
15	1		*FRONT GRILLE / CAA	0.00	0.00	*545.00 F
16	1		*FRONT GRILLE TOP BEAM ?	0.00	0.00	*150.00 F
17	1		*FRONT BUMPER TOP RUBBER / TN	0.00	0.00	*20.00 F
18	1		*FRONT GRILLE CAMERA / cut	0.00	0.00	*860.00 F
19	1		*FRONT HEADLAMP RH / CAA	0.00	0.00	*1,800.00 F
20	1		*FRONT HEADLAMP LH	0.00	0.00	*1,800.00 F
21	1		*FRONT FENDER RH / X	0.00	0.00	*650.00 F
22	10		*FRONT FENDER SHIELD CLIP / X	0.00	0.00	*60.00 F
23	1		*FRONT BUMPER / de	0.00	0.00	*850.00 F
24	1		*FRONT BUMPER CARRIER CENTRE ?	0.00	0.00	*80.00 F
25	1		*FRONT BUMPER CARRIER RH ?	0.00	0.00	*50.00 F
26	1		*FRONT BUMPER CARRIER LH ?	0.00	0.00	*50.00 F
27	1		*FRONT BUMPER FOAM ?	0.00	0.00	*110.00 F
28	1		*FRONT BUMPER REINFORCEMENT / BT	0.00	0.00	*315.00 F
29	1		*FRONT BUMPER REINFORCEMENT BRACKET RH ?	0.00	0.00	*145.00 F
30	1		*FRONT BUMPER REINFORCEMENT BRACKET LH ?	0.00	0.00	*145.00 F
31	1		*FRONT BUMPER LOWER GRILLE ?	0.00	0.00	*65.00 F
32	1		*FRONT BUMPER FOGLAMP COVER RH ?	0.00	0.00	*60.00 F
33	1		*FRONT BUMPER FOGLAMP COVER LH X	0.00	0.00	*60.00 F
34	1		*FRONT BUMPER FOGLAMP CHROME RH ?	0.00	0.00	*50.00 F
35	1		*FRONT BUMPER FOGLAMP CHROME LH X	0.00	0.00	*50.00 F
36	1		*FRONT BUMPER LOWR GARNISH / CAA	0.00	0.00	*85.00 F
37	1		*FRONT BUMPER LOWER GARNISH CHROME / BR	0.00	0.00	*85.00 F
38	1		*AIR BUFLER TOP ?	0.00	0.00	*80.00 F
39	1		*AIR BUFLER LOWER ?	0.00	0.00	*95.00 F
40	1		*AIR CON CONDENSER ?	0.00	0.00	*885.00 F
41	1		*RADIATOR ?	0.00	0.00	*600.00 F
42	1		*RADIATOR FAN ASSY ?	0.00	0.00	*1,000.00 F
43	1		*FRONT NUMBER PLATE GARNISH / CAA	0.00	0.00	*68.00 F
44	10		*FRONT BUMPER CLIP / KCL	0.00	0.00	*60.00 F

F=Franchise part.

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Sub Total (S\$)						14,761.00
+ Margin on L,N Items 10.00% (S\$)						1,476.10
Total Parts (S\$)						16,237.10

Kan Fook Sing Motor Workshop/SLG1485Z/03/10/2022 12:40. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE / BT	40.00
Sub Total (S\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New 900 800	980.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New 30	50.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New ✓	100.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New 700	880.00
Gross Labour Cost (S\$)			2,010.00

Kan Fook Sing Motor Workshop/SLG1485Z/03/10/2022 12:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Excess: TBA
Not Authorised.
5 Days
Part by mt.
Euro Q34
8288 0282
4/10/22

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is done on "not prejudice" basis
- No illegal modification allowed
- Supplemental work is subject to approval and is subject to the insurance Company

Acknowledged by Repairer:

Signature:

Date: