

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22009703/TWY3Q2**Date:** 14/11/2022REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MN000293

**Claimant Vehicle No :** SH7653C**Insured Vehicle No :** SLP8636L

Date of Loss: 28/09/2022

Nature of Claim: TP Claim No: M2205444

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SH7653C**

Make &amp; Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEJU192179

Reg. Date: 23/04/2019 (Man. Year: 2019)

Chassis No: KMH851CVKU141654

Colour: Blue

Odometer: 426344 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,485.56	378.60	1,106.96	74.51
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	760.00	630.00	130.00	17.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,256.56</b>	<b>1,019.60</b>	<b>1,236.96</b>	<b>54.82</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>800.00</b>		
<b>(\$\$)</b>	2,256.56	800.00	1,456.56	64.55
<b>+ GST 7.00/7.00% (\$\$)</b>	157.96	56.00	101.96	64.55
<b>Nett Amount (\$\$)</b>	<b>2,414.52</b>	<b>856.00</b>	<b>1,558.52</b>	<b>64.55</b>

INSPECTION

Date of Assignment: 03/10/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 03/10/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2022)
<b>Parts:</b>	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SH7653C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
6	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
7	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	180.00 F	*- F
8	1		*REAR NUMBER PLATE WITH TRIM COVER	Not Necessary	50.00 F	*- F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,799.45</b>	<b>473.25</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	313.89	94.65
<b>Total Parts (\$\$)</b>	<b>1,485.56</b>	<b>378.60</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (\$\$)			760.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >