Adjuster Report 11/15/22, 12:44 PM

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22009716/DWY3Q2

15/11/2022 Date:

**REFERENCE** 

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

**Claimant Vehicle** SLQ5834X Insured Vehicle No: **SLT1387E** No:

28/09/2022 Nature of Claim: TP Claim No: N/A Date of Loss:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLQ5834X** 

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: LEB5948293 Reg. Date: 14/07/2017 (Man. Year: 2017) Chassis No: RU31248277 Colour: Odometer: 627886 km Silver

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Rear Left Side: Triangle 5 mm Triangle 5 mm Triangle 5 mm Front Right Side: Triangle 5 mm Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,469.20	2,637.16	2,832.04	51.78
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,005.00	1,240.00	1,765.00	58.74
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculate	ed Gross Total (S\$)	8,474.20	3,877.16	4,597.04	54.25
Approved Tota	l (Overridden) (S\$)		3,100.00		
	Nett Amount (S\$)	8,474.20	3,100.00	5,374.20	63.42
	Global Sum Settlement (S\$)		0.00		

**INSPECTION** 

Date of Assignment: 03/10/2022

Lian Her Motors (Ang Mo Kio)

Blk 5038, Ang Mo Kio Industrial Park 2, #01-405 Date Inspected: 25/10/2022 Inspected At:

Singapore 569541

Estimated Period of Repair: 4.0 days

Adjuster: **BRYAN TANI** Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

C = = = 1:4: = =

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2022)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ5834X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	855.60 FL	*762.70 FL
2	1		*REAR N/S SIDE BUMPER	Serviceable	335.60 FL	*- FL
3	1		*REAR N/S BUMPER SIDE RETAINER	Serviceable	55.10 FL	*- FL
4	1		*REAR N/S FENDER ARCH PROTECTOR	Cut	175.20 FL	*175.20 FL
5	1		*REAR N/S DOOR	Dented	986.80 FL	*986.80 FL
6	1		*REAR N/S DOOR INNER TRIM BOARD	Mtg Broken	485.20 FL	*485.20 FL
7	1		*REAR N/S DOOR GLASS REGULATOR	Not Necessary	176.50 FL	*- FL
8	1		*REAR N/S DOOR GLASS REGULATOR MOTOR	Not Necessary	468.80 FL	*- FL
9	1		*REAR N/S DOOR RUBBER	Not Necessary	125.60 FL	*- FL
10	1		*REAR N/S ROCKER PANEL GARNISH	Repair	455.70 FL	*- FL
11	1		*REAR N/S SHOCK ABSORBER	Not Necessary	385.10 FL	*- FL
12	1		*REAR N/S HUB ASSY	Damaged	355.60 FL	*305.30 FL
13	1		*REAR AXLE	Not Necessary	1,250.70 FL	*- FL
14	1		*REAR N/S TYRE RIM	Cut	550.00 FS	*450.00 FS
15	15		*CLIP	Necessary	30.00 FS	*15.00 FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	6,691.50	3,180.20
			- List Item Discount on L Items	20.00/20.00% (S\$)	1,222.30	543.04
				Total Parts (S\$)	5,469.20	2,637.16
			Report was unsubmitted during this prir	nt-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$	New	1,000.00	500.00
2	TO PUTTY AND SPRAY PAINT	New	1,000.00	500.00
3	CHECK & RECONNECT WIRING	New	45.00	0.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	180.00	40.00
5	REMOVE/REFIT REAR N/S DOOR MECHANISMAND GLASS TO NEW DOOR	New	150.00	60.00
6	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	100.00	0.00
7	REMOVE/RENEW REAR AXLE ,HUB AND SHOCK ABSORBER	New	450.00	80.00
8	CHECK AND REALIGN WHEEL ALIGNMENT	New	80.00	60.00
	Gross Labour		3,005.00	1,240.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >