

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22009722/TNY3Q2**Date:** 01/12/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	PL001281
Claimant Vehicle No :	SLB3121L	Insured Vehicle No :	
Date of Loss:	27/09/2022	Nature of Claim:	TP
		Claim No:	PLC01049

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB3121L		
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT AWD S/R FACELIFT (A)	Engine No:	4B12QS5384
Reg. Date:	01/04/2016 (Man. Year: 2015)	Chassis No:	JMYXTGF3WGW002559
Colour:	Silver	Odometer:	103084 km
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	300.00	700.00	70.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,000.00	300.00	700.00	70.00
+ GST 7.00/7.00% (S\$)	70.00	21.00	49.00	70.00
Nett Amount (S\$)	1,070.00	321.00	749.00	70.00

INSPECTION

Date of Assignment:	03/10/2022	Present Location:	Wah Hong Motors & Credit Pte Ltd (HQ)
Date Inspected:	05/10/2022	Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Dec 2022)		
Parts:	M1-SUV MITSUBISHI OUTLANDER 2.4 CVT AWD S/R FACELIFT (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLB3121L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Roof panel (Repair refer to labor) (NPA)	Repair	0.00 F	*- F
2	1		*Roof lining garnish RH (Repair refer to labor) (NPA)	Repair	0.00 F	*- F
F=Franchise part.						
Sub Total (S\$)					0.00	0.00
+ Margin on L,N Items 5.00/5.00% (S\$)					0.00	0.00
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	500.00	100.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	500.00	200.00
Gross Labour Cost (\$\$)			1,000.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >