



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCR 136L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	BADLY DENTED	1,202.80	1,202.80
1	REAR TAILGATE LOCK	DENTED / JAMMED	165.80	165.80
1	REAR TAILGATE CENTER OUTER GARNISH	WARPED	442.30	442.30
1	REAR TAILGATE WEATHERSTRIP RUBBER	NOT NECESSARY	139.30	-
1	REAR TAILGATE "AIRWAVE" EMBLEM	NECESSARY	68.30	68.30
1	REAR BUMPER	DENTED / DEFORMED	936.30	936.30
1	END PANEL	TO REPAIR SEE LABOUR	575.30	-
1	END PANEL TOP GARNISH	NOT NECESSARY	86.20	-
1	REAR WINDSCREEN MOULDING	NECESSARY	58.50	58.50
1	SPARE TYRE PANEL (NPA)	NOT NECESSARY	-	-
	LESS 20% DISCOUNT		-734.96	-574.80
			2,939.84	2,299.20
	<u>SPECIAL NETT ITEMS</u>			
20	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	40.00
1	SEALANT (SN)	NECESSARY	60.00	40.00
			110.00	80.00
	<u>LABOUR</u>			
	REMOVE AND REFIX REAR SCREEN.		120.00	120.00
	SPRAY PAINTING.		1,200.00	680.00
	TUFF COAT.		100.00	30.00
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF END PANEL.		1,550.00	400.00
	WIRING.		40.00	20.00
			3,010.00	1,250.00
	GRAND TOTAL		6,059.84	3,629.20



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00
---	--	--	-----------------

Report Ref No. CS/AGI22009723/Uny3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.