

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22009725/UCY3M4**Date:** 12/10/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1002061230

Claimant Vehicle No : SLL9014X**Insured Vehicle No :** SMM4485K

Date of Loss: 30/09/2022

Nature of Claim: TP

Claim No: 286530

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLL9014X**

Make & Model: HONDA HR-V, 1.5 DX CVT (A)

Engine No: L15B4532054

Reg. Date: 15/03/2017 (Man. Year: 2016)

Chassis No: JHMRU1810GX202054

Colour: Red

Odometer: 46772 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,397.28	2,189.76	3,207.52	59.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	1,440.00	1,290.00	47.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,127.28	3,629.76	4,497.52	55.34
Approved Total (Overridden) (\$\$)		2,900.00		
(\$\$)	8,127.28	2,900.00	5,227.28	64.32
+ GST 7.00/7.00% (\$\$)	568.91	203.00	365.91	64.32
Nett Amount (\$\$)	8,696.19	3,103.00	5,593.19	64.32

INSPECTION

Date of Assignment: 04/10/2022

Date Inspected: 04/10/2022 Inspected At:

Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI
BUKIT
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Oct 2022)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL9014X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	734.80 FL	*524.30 FL
2	1		*FRONT BUMPER LOWER	Distorted	472.40 FL	*387.10 FL
3	1		*FRONT BUMPER CENTRE GRILLE	Distorted	296.30 FL	*87.10 FL
4	1		*FRONT BUMPER FOG LAMP AND COVER RH (2PCS)	Twisted	996.80 FL	*261.60 FL
5	1		*FRONT BUMPER RETAINER RH	Cracked	24.30 FL	*24.30 FL
6	1		*FRONT BUMPER SPONGE	No such part	267.50 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	495.40 FL	*266.10 FL
8	2		*FRONT BUMPER SENSOR	Not fitted	400.00 FL	*- FL
9	10		*FRONT BUMPER CLIP	Necessary	55.00 FL	*30.00 FL
10	1		*FRONT HEADLAMP RH	Cracked	1,128.30 FL	*1,128.30 FL
11	1		*FRONT HEADLAMP LOWER BRACKET RH	Cracked	87.30 FL	*28.40 FL
12	1		*FRONT FENDER RH	Repair	615.30 FL	*- FL
13	1		*FRONT FENDER COWLING RH	Not Necessary	123.10 FL	*- FL
14	10		*FRONT FENDER COWLING CLIP	Not Necessary	55.00 FL	*- FL
15	1		*FRONT FENDER TOP GARNISH RH	Not Necessary	28.30 FL	*- FL
16	2		*FRONT FENDER TOP GARNISH CLIP RH	Not Necessary	11.00 FL	*- FL
17	1		*FRONT FENDER INNER PANEL RH	Repair	286.40 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Repair	669.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,746.60	2,737.20
- List Item Discount on L Items 20.00/20.00% (S\$)	1,349.32	547.44
Total Parts (S\$)	5,397.28	2,189.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT DAMAGE PARTS, TO CUT/WELD KNOCK AND REALIGN ACCIDENT AGGECTED AREA	New	1,200.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,200.00	750.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	150.00	0.00
4	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	60.00	20.00
5	TO CHECK WHEEL ALIGNMENT	New	120.00	70.00
Gross Labour Cost (\$\$)			2,730.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >