

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22009726/Rny3e2	
	300 BEACH ROAD			Date:	11/10/2022	
	#17-04/07 THE CO	NCOURSESINGAPORE 199555		0	LDCC	
4		Dell'es Best'estess	(TIUDD DADT	Code:		
1.	,					
	Insured Veh.	SFB 6883Y	Veh. Inspected	<u> </u>	SFL 3131B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/VP05/026363	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		03/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA CAMRY 2.0 A	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	MR053BK4107020292	Colour		GREY	
	Odometer	191064 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	BRIDGESTONE		6 mm	
	L/H Front Tyre	215/60 R16	BRIDGESTONE		6 mm	
	R/H Rear Tyre	215/60 R16	BRIDGESTONE		6 mm	
	L/H Rear Tyre	215/60 R16	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
5.	General Information					
	Accident Date	02/10/2022	Inspect Date /	Time	05/10/2022 (11:43 AM)	
	Survey held at	HONG MOTOR SERVICES				
		BLK 5035 ANG MO KIO IND PARK 2 #01-365 SINGAPORE 569538				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22009726/Rny3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser