

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI22009727/SNY3E2
Date: 09/11/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSNA00240172105	
Claimant Vehicle No : FBR5412T	Insured Vehicle No : SLJ2959B	
Date of Loss: 27/09/2022	Nature of Claim: TP	Claim No: SNM22D206906/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR5412T		
Make & Model:	ROYAL ENFIELD CONTINENTAL GT 650, 648cc	Engine No:	P7A6FBL1052931
Reg. Date:	28/07/2020 (Man. Year: 2020)	Chassis No:	ME3CNEG6TLK050809
Colour:	White	Odometer:	80477 km
Engine Capacity:	648 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/90-18	Rear Tyre Size:	130/90-18
Front Left Side:	Trail Blazer 6 mm	Rear Left Side:	Trail Blazer 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/10/2022	
Date Inspected:	03/10/2022	Inspected At: S1 Motoring (HQ) BLOCK 3006 UBI ROAD 1, #01-366 Singapore 408700
Estimated Period of Repair:	2.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00
-\$1,500.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Nov 2022)	
Parts:	N/A	ROYAL ENFIELD CONTINENTAL GT 650 648cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR5412T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >