

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22009734/KPA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220066133
Claimant Vehicle No :	SHD5322Y	Insured Vehicle No :	SNB182G
Date of Loss:	26/09/2022	Nature of Claim:	TP
		Claim No:	3577916349SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5322Y		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B94514
Reg. Date:	11/01/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU603078747
Colour:	Metallic Pearl White/Red	Odometer:	299750 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 8 mm	Rear Left Side:	Wanli 8 mm
Front Right Side:	Wanli 8 mm	Rear Right Side:	Wanli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,631.77	1,220.62	4,411.15	78.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,990.00	660.00	4,330.00	86.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,621.77	1,880.62	8,741.15	82.29
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	10,621.77	1,500.00	9,121.77	85.88
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	28/09/2022		
Date Inspected:	28/09/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Buckled	516.00 FL	*516.00 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	80.10 FL	*80.10 FL
3	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	716.60 FL	*- FL
4	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL
5	1		*LAMP ASSY ,FOG ,RH	Cut	951.40 FL	*951.40 FL
6	1		*UNIT ASSY ,HEADLAMP, RH	Serviceable	2,637.60 FL	*- FL
7	1		*COVER ,FRONT BUMPER HOLE ,RH	Serviceable	29.30 FL	*- FL
8	1		*JAR ASSY ,WINDSHIELD WASHER	Serviceable	219.10 FL	*- FL
9	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	346.00 FL	*- FL
10	1		*EMBLEM ASSY, RADIATOR GRILLE	Serviceable	90.80 FL	*- FL
11	1		*GRILLE ,RADIATOR ,LOWER NO.1	Serviceable	170.10 FL	*- FL
12	1		*FENDER SUB-ASSY ,FRONT RH	Repair	977.80 FL	*- FL
13	1		*LINER ,FRONT FENDER, RH	Serviceable	206.70 FL	*- FL
14	1		*FRONT FENDER EMBLEM RH	Not Necessary	54.60 FL	*- FL
15	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
16	1		*FRT NUMBER PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
17	1		*FRT BUMPER SIDE RETAINER CLIP	Not Necessary	65.00 FS	*- FS
18	1		*FENDER LINER CLIP	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,400.70	1,607.50
- List Item Discount on L Items 25.00/25.00% (\$)	1,768.93	386.88
Total Parts (\$)	5,631.77	1,220.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	440.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	200.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
			Gross Labour Cost (S\$)	4,990.00
				660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >