



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 777K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	16,000.00	16,000.00
1	BUMPER SPONGE	CRACKED	1,050.00	1,050.00
2	BUMPER BRACKET @\$280.00	NOT NECESSARY	560.00	-
1	NOVITEC FRONT SPOILER IN CF, RH ONLY FOR LP700	CRACKED	2,750.00	2,750.00
1	NOVITEC FRONT SPOILER IN CF, LH ONLY FOR LP700	CRACKED	2,750.00	2,750.00
1	NOVITEC FRONT STRUT IN CF FOR LP700	CRACKED	3,150.00	3,150.00
1	BUMPER CENTRE GRILLE	CRACKED	450.00	450.00
2	BUMPER PARKING SENSOR @\$220.00 (2 FAULTY REQUIRED TO REPLACEMENT)	NOT WORKING	440.00	440.00
1	BUMPER EMBLEM	CUT	650.00	650.00
1	FRONT WHEEL HOUSING RH	NOT NECESSARY	1,720.00	-
			29,520.00	27,240.00
	<u>LABOUR</u>			
	LABOUR FOR INSTALLATION & PAINTWORK & STICKER WRAP.		1,500.00	1,500.00
			1,500.00	1,500.00
	GRAND TOTAL		31,020.00	28,740.00
	RECOMMENDED COST OF REPAIRS			28,740.00

Report Ref No. CS/LAW22009735/Tqy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.