

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22009741/EPA3Q2**Date:** 10/04/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	.
Claimant Vehicle No :	SKS8866K	Insured Vehicle No :	SMR267Z
Date of Loss:	01/10/2022	Nature of Claim:	TP Claim No: MFL2022D0005519

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS8866K	Engine No:	DFY069503
Make & Model:	VOLKSWAGEN GOLF, 1.5 LIFE ETSI (A)	Chassis No:	WVWZZZCDZMW356842
Reg. Date:	13/07/2021 (Man. Year: 2021)	Odometer:	17836 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Firestone 4 mm	Rear Left Side:	Firestone 4 mm
Front Right Side:	Firestone 4 mm	Rear Right Side:	Firestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,463.78	2,334.89	1,128.89	32.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,396.00	3,040.00	2,356.00	43.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,859.78	5,374.89	3,484.89	39.33
+ GST 7.00/7.00% (S\$)	620.18	376.24	243.94	39.33
Nett Amount (S\$)	9,479.96	5,751.13	3,728.83	39.33
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,186.58		

INSPECTION

Date of Assignment:	04/10/2022	
Date Inspected:	05/10/2022	Inspected At: Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2022)
Parts:	144	VOLKSWAGEN GOLF 1.5 LIFE ETSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS8866K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Dented	1,140.21 FS	*1,140.21 FS
2	1		*GUIDE PIECE LHR BUMPER BRACKET- (SIDE)	Not Necessary	37.70 FS	*- FS
3	1		*GUIDE PIECE RHR BUMPER BRACKET- (SIDE)	Not Necessary	37.70 FS	*- FS
4	1		*GUIDE PIECE LHR BUMPER BRACKET (OUTER)	Not Necessary	37.70 FS	*- FS
5	1		*GUIDE PIECE RHR BUMPER BRACKET (OUTER)	Not Necessary	37.70 FS	*- FS
6	1		*ATTACHMENT STRIP RR BUMPER BRACKET (CENTER)	Not Necessary	61.42 FS	*- FS
7	1		*SENSOR PRIMED	Not Necessary	171.16 FS	*- FS
8	1		*SEAL RING SATIN BLACK (4 PCS)	Necessary	16.99 FS	*16.99 FS
9	1		*SENSOR BRACKET	Necessary	11.60 FS	*11.60 FS
10	2		*SENSOR BRACKET	Necessary	23.20 FS	*23.20 FS
11	1		*SENSOR BRACKET	Necessary	11.60 FS	*11.60 FS
12	1		*2K-PLASTIC ADHESIVE	Necessary	77.35 FS	*77.35 FS
13	1		*BONDING AGENT FOR PLASTIC	Necessary	61.97 FS	*61.97 FS
14	1		*BUMPER REINFORCEMENT	Not Necessary	487.90 FS	*- FS
15	1		*REAR DIFFUSOR SATIN BLACK	Cut	250.31 FS	*250.31 FS
16	1		*RIVET (3 PCS)	Necessary	3.56 FS	*3.56 FS
17	1		*REFLECTOR RHR	Not Necessary	71.14 FS	*- FS
18	1		*REFLECTOR LHR	Not Necessary	71.14 FS	*- FS
19	2		*LED LICENCE PLATE LIGHT	Not Necessary	115.33 FS	*- FS
20	1		*REAR NUMBER PLATE	Bent	76.00 FS	*76.00 FS
21	1		*INSCRIPTION BRIGHT CHROME GOLF LETTERING (SCK)	Necessary	70.01 FS	*70.01 FS
22	1		*INSCRIPTION BRIGHT CHROME ETSI LETTERING (SCK)	Necessary	70.01 FS	*70.01 FS
23	1		*BUMPER REINFORCEMENT	Bent	500.17 FS	*500.17 FS
24	1		*BOLT FOR SPARE WHEEL MOUN	Broken	21.91 FS	*21.91 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **3,463.78** **2,334.89**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	2,394.00	798.00
2	SPRAY PAINTING	New	2,280.00	1,520.00
3	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	266.00	266.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	456.00	456.00
Gross Labour Cost (\$\$)			5,396.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >