

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22009746/KPA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000070
Claimant Vehicle No :	SJJ4011X	Insured Vehicle No :	GBH5202K
Date of Loss:	03/10/2022	Nature of Claim:	TP
		Claim No:	3054567997SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ4011X	Engine No:	1NZX805694
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305080045
Reg. Date:	11/09/2008 (Man. Year: 2008)	Odometer:	183273 km
Colour:	Metallic Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 3 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,167.77	3,703.50	4,464.27	54.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,820.00	1,440.00	44.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,427.77	5,523.50	5,904.27	51.67
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	11,427.77	4,300.00	7,127.77	62.37
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		5,213.45		
Global Sum Settlement (S\$)		5,200.00		

INSPECTION

Date of Assignment:	04/10/2022		
Date Inspected:	04/10/2022	Inspected At:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01 Singapore 575721
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	695.60 FL	*695.60 FL
2	1		*REAR BOOT LOCK	Dented	178.40 FL	*178.40 FL
3	1		*REAR BOOT LOCK CATCH	Repair	52.10 FL	*- FL
4	1		*REAR BOOT WEATHERSTRIP (50%)	Dented / Cut	197.33 FS	*131.55 FS
5	1		*REAR BOOT OUTER MOULDING	Warped	243.20 FL	*243.20 FL
6	2		*REAR BOOT HINGES	Repair	284.40 FL	*- FL
7	1		*REAR BOOT KEY CYLINDER	Serviceable	256.00 FL	*- FL
8	2		*REAR BOOT NUMBER PLATE LAMP	Serviceable	356.20 FL	*- FL
9	1		*REAR BOOT EMBLEM E	Not Necessary	64.20 FL	*- FL
10	1		*REAR BOOT EMBLEM VIOS	Necessary	66.20 FL	*66.20 FL
11	1		*REAR BOOT EMBLEM LOGO	Necessary	58.30 FL	*58.30 FL
12	1		*REAR BOOT SIDE FOAM BOX	Cracked	165.50 FL	*165.50 FL
13	1		*REAR BUMPER	Bent	527.60 FL	*503.20 FL
14	2		*REAR BUMPER SIDE RETAINER	Distorted	92.60 FL	*92.60 FL
15	2		*REAR BUMPER BRACKET	Repair	156.80 FL	*- FL
16	1		*REAR BUMPER DUST COVER	Serviceable	164.30 FL	*- FL
17	16		*REAR BUMPER CLIP	Necessary	41.60 FL	*41.60 FL
18	1		*REAR BUMPER REFLECTOR	N/S Mtg Cracked/O/SServiceable	430.00 FL	*105.00 FL
19	2		*REAR TAIL LAMP ASSY	Cracked	1,039.20 FL	*744.00 FL
20	2		*REAR TAIL LAMP HOUSING PANEL	Repair	625.00 FL	*- FL
21	1		*REAR END PANEL	Bent	526.25 FL	*439.00 FL
22	1		*REAR END PANEL TOP GARNISH	Dented	247.30 FL	*230.00 FL
23	1		*REAR SPARE TYRE PANEL	Repair	764.60 FL	*- FL
24	1		*REAR SPARE TYRE TOP BOARD	Serviceable	315.20 FL	*- FL
25	1		*REAR EXHAUST SILENCER	Repair	956.70 FL	*- FL
26	1		*REAR BUMPER LOWER PAD	Bent	1,200.00 FS	*700.00 FS
27	1		*SET REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
28	1		*SET REVERSE SENSOR	Dented	220.00 FS	*200.00 FS
29	1		*TYRE -BRIDGESTONE RE004	Serviceable	260.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,244.58	4,594.15
- List Item Discount on L Items 25.00/25.00% (\$)	2,076.81	890.65
Total Parts (\$)	8,167.77	3,703.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,200.00	700.00
2	TO CHECK WIRING SYSTEM	New	60.00	20.00
3	TO INSTALL REVERSE SENSOR	New	80.00	50.00
4	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	900.00
5	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	150.00	60.00
6	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	150.00	30.00
7	TO REMOVE CARPET ,TRIMMING AND SEATS TO ENABLE REPAIR	New	120.00	60.00
8	TO BENCH PULL CHASSIS ALIGNMENT AND REALIGN	New	400.00	0.00
9	TOWING-KING DOLLY	New	100.00	0.00
Gross Labour Cost (S\$)			3,260.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >