

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EQI22009750/TWY3M4**Date:** 28/12/2022REFERENCE

Handling Insurer: EQ Insurance Company Ltd Policy No:
Claimant Vehicle No : SHB6253S **Insured Vehicle No :** SMG9792Y
 Date of Loss: 03/10/2022 Nature of Claim: TP Claim No: DM22HO01691

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB6253S**
 Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) Engine No: G4LEJU045572
 Reg. Date: 03/07/2018 (Man. Year: 2018) Chassis No: KMHC851CVJU103381
 Colour: Blue Odometer: 437921 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,435.56	558.60	876.96	61.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	830.00	150.00	15.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,415.56	1,388.60	1,026.96	42.51
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	2,415.56	1,100.00	1,315.56	54.46
+ GST 7.00/7.00% (S\$)	169.09	77.00	92.09	54.46
Nett Amount (S\$)	2,584.65	1,177.00	1,407.65	54.46

INSPECTION

Date of Assignment: 04/10/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
 Date Inspected: 04/10/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts: 143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB6253S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER COVER	Repair	459.40 FL	*- FL	
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL	
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL	
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL	
5	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL	
6	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL	
7	1		*REAR BUMPER REVERSE SENSOR	Not Working	180.00 F	*180.00 F	
					Sub Total (S\$)	1,749.45	653.25
					- List Item Discount on L Items 20.00/20.00% (S\$)	313.89	94.65
					Total Parts (S\$)	1,435.56	558.60

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ADVERTISEMENT STICKER LH RH (Necessary)	New	200.00	200.00
2	PANEL BEATING	New	400.00	350.00
3	SPRAY PAINTING CHARGE	New	300.00	250.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
			Gross Labour Cost (S\$)	980.00
				830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >