



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 3788L

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | FRONT SIDE MIRROR RH | DISTORTED | 847.73 | 847.73 |
| 1 | FRONT SIDE MIRROR COVER RH | MISSING | 111.97 | 111.97 |
| 1 | FRONT SIDE MIRROR GLASS RH | NOT NECESSARY | 139.52 | - |
| 1 | FRONT SIDE MIRROR SIGNALLAMP RH | CRACKED | 69.34 | 69.34 |
| | LESS 25% DISCOUNT | | -292.14 | -257.26 |
| | | | 876.42 | 771.78 |
| LABOUR | | | | |
| | TO CHECK WIRING SYSTEM. | NOT NECESSARY | 50.00 | - |
| | TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS. | | 300.00 | 100.00 |
| | SPRAYPAINTING CHARGES. | | 300.00 | 100.00 |
| | | | 650.00 | 200.00 |
| GRAND TOTAL | | | 1,526.42 | 971.78 |

| | | | | |
|---|--|--|--|---------------|
| RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) | | | | 971.78 |
|---|--|--|--|---------------|

Report Ref No. CS/SPF22009754/Gvy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$971-\$1,000

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.