

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009757/APA3Q2
Date: 18/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000064
Claimant Vehicle No :	SLN8399G	Insured Vehicle No :	GBL2530L
Date of Loss:	03/10/2022	Nature of Claim:	TP
		Claim No:	4757522562SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8399G	Engine No:	27492030870190
Make & Model:	MERCEDES-BENZ E250, 2.0 AVG (R18 LED) (A)	Chassis No:	WDD2130452A136876
Reg. Date:	18/05/2017 (Man. Year: 2016)	Odometer:	44962 km
Colour:	Green		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/40 R18	Rear Tyre Size:	275/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,964.00	10,147.70	6,816.30	40.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	2,110.00	1,890.00	47.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,964.00	12,257.70	8,706.30	41.53
Approved Total (Overridden) (\$\$)		9,800.00		
Nett Amount (\$\$)	20,964.00	9,800.00	11,164.00	53.25
+ Loss of Use (7.0 x S\$100.00/day) (\$\$)		700.00		
Nett Liability (\$\$)		10,500.00		

INSPECTION

Date of Assignment:	04/10/2022	
Date Inspected:	04/10/2022	Inspected At: ADVANCE AUTO GARAGE (23 KAKI BUKIT) (HQ) 25 KAKI BUKIT AVE 4 #04-01 VICOM KAKI BUKIT Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,874.00 F	*1,874.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	384.00 F	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Cut	485.00 F	*485.00 FL
5	1		*REAR BUMPER LOWER GARNISH CHROME MOULDING	Cracked	291.00 F	*291.00 FL
6	2		*REAR BUMPER EXHAUST CHROME PIPE	Not Necessary	462.00 F	*- FL
7	2		*REAR BUMPER REFLECTOR	Not Necessary	138.00 F	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Dented	846.00 F	*846.00 FL
9	2		*REAR BUMPER EXHAUST CHROME PIPE BRACKET	Cracked	64.00 F	*64.00 FL
10	1		*REAR BUMPER CENTRE GUIDE	Cracked	275.00 F	*275.00 FL
11	1		*REAR BUMPER REINFORCEMENT COVER	Cracked	149.00 F	*149.00 FL
12	1		*REAR BUMPER KICK SENSOR	Not Necessary	316.00 F	*- FL
13	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,072.00 F	*536.00 FL
14	4		*REVERSE SENSOR HOLDER	Necessary	100.00 F	*100.00 FL
15	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	622.00 F	*- FL
16	2		*TAILLAMP	Cracked	1,570.00 F	*1,570.00 FL
17	2		*TAILLAMP LOWER BRACKET	Cracked	154.00 F	*154.00 FL
18	1		*BOOTLID	Dented	2,399.00 F	*2,399.00 FL
19	1		*BOOTLID LOCK	Damaged	294.00 F	*294.00 FL
20	1		*BOOTLID WEATHERSTRIPE	Cut	292.00 F	*292.00 FL
21	1		*BOOTLID OUTER CHROME MOULDING	Cut	267.00 F	*267.00 FL
22	1		*MERCEDES BENZ LOGO	Necessary	93.00 F	*93.00 FL
23	1		*E250 WORDING	Necessary	97.00 F	*97.00 FL
24	1		*CYCLE AND CARRIAGE LOGO	Necessary	45.00 F	*45.00 FL
25	1		*9 G TRONIC WORIDNG	Necessary	95.00 F	*95.00 FL
26	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	710.00 F	*- FL
27	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	1,310.00 F	*- FL
28	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
29	1		*REAR CAMERA	Not Necessary	859.00 F	*- FL
30	1		*REAR END PANEL	Dented	1,302.00 F	*998.00 FL
31	1		*REAR END PANEL TOP GARNISH	Deformed	229.00 F	*229.00 FL
32	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,964.00	11,263.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,115.30
Total Parts (\$\$)	16,964.00	10,147.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	1,000.00
2	SPRAY PAINTING	New	1,400.00	800.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
9	TO PERFORM DIANOGSTIC TEST	New	250.00	0.00
Gross Labour Cost (S\$)			4,000.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >